



Phase 2 Evaluation and Engineering Assessment and Golf Course Renovation Harry L. Jones Sr. Golf Course

Ratcliffe Golf Services, Inc.
800 Radio Road
Charlotte, North Carolina 28216

02217302.00 | October 2, 2018

SCS ENGINEERS P.C.

2520 Whitehall Park Drive, Suite 450
Charlotte, NC 28273
704-504-3107

Table of Contents

| Section | Page |
|--|------|
| 1 INTRODUCTION AND BACKGROUND..... | 1 |
| Background | 1 |
| Phase 1 Report Overview | 1 |
| Phase 2 Report Overview | 2 |
| 2 DRILLING PROGRAM..... | 3 |
| 3 SOIL SURCHARGE ANALYSIS | 4 |
| Overview | 4 |
| Typical Soil Surcharge Approach..... | 4 |
| Cart Paths..... | 7 |
| 4 SOIL STOCKPILE ASSESSMENT..... | 8 |
| 5 PERMITTING REQUIREMENTS | 9 |
| 6 PROPOSED GOLF COURSE RENOVATION BY RON GARL GOLF DESIGN..... | 10 |
| Overview | 10 |
| Course Design – The Theme: The Journey with Harry L. Jones, Sr. Golf Course..... | 10 |
| The Design – The Master Plan | 11 |
| 7 COST ESTIMATES | 12 |
| Golf Course Closure | 12 |
| Golf Course Renovation Cost Estimate..... | 12 |
| 8 FINANCIAL PROJECTIONS AND FEASIBILITY ANALYSIS..... | 13 |
| Overview | 13 |
| Analysis: Option 1, Close the Course | 13 |
| Analysis: Option 2, Close 9 Holes, Renovate the Remaining 9 Holes | 14 |
| Analysis: Option 3, Renovate all 18 Holes..... | 14 |
| 9 CONCLUSION AND NEXT STEPS – PHASE III | 16 |

Figures

| | |
|---|---|
| Figure 1. Typical Settlement Plate Details | 5 |
| Figure 2. Surcharge Settlement Monitoring Example | 6 |

Appendices

| | |
|------------|---------------------------------------|
| Appendix A | Drilling Work Plan and Boring Results |
| Appendix B | Golf Course Routing Plan |
| Appendix C | Preliminary Cost Estimates |

1 INTRODUCTION AND BACKGROUND

Mecklenburg Park and Recreation Department has determined that significant issues are affecting the operation of one of their public golf facilities, the Harry L. Jones, Sr. Golf Course located at 1525 W. Tyvola Rd., Charlotte, NC 28217. They have directed Ratcliffe Golf Services (Ratcliffe), the firm contracted with managing the property, to move forward with an evaluation to determine the best course of action for the facility. Ratcliffe retained SCS Engineers, PC to provide engineering services, Ron Garl Golf Design to serve as golf course architect, and. JJKeegan+ to conduct a financial analysis of each alternative proposed in the study.

This report, Phase 2 Evaluation and Engineering Assessment and Golf Course Renovation, was prepared by SCS Engineers, Ron Garl Golf Design and JJKeegan+. This report provides following:

- A summary of our field investigation activities
- Results from our drilling program
- An engineering approach to mitigate settlement due to waste decomposition
- Permitting requirements
- Proposed golf course renovation design
- Construction cost estimates
- Summary of the JJKeegan+ financial feasibility analysis
- Discussion and proposals for next steps (Phase III).

BACKGROUND

The Harry L. Jones Sr. Golf Course (formerly named Renaissance Park Golf Course) is located at 1525 West Tyvola Road in Charlotte North Carolina. The course is owned by the City of Charlotte (City) and managed by the Mecklenburg County Parks and Recreation Department (MCPR). The golf course was designed by golf course architect Mike Hurdzan and built in 1986.

Prior to redevelopment of the property as a golf course, the site was a municipal solid waste disposal facility known as the York Road Landfill. The City operated the landfill from approximately 1968 to 1986. Approximately 6 million tons of waste are reported to have been disposed at the landfill¹. No waste has been removed from site to our knowledge and it was closed and capped in 1987. The waste disposal operations have been reported by others as occurring in six areas, referred to as Area A through Area F. Based on the historical disposal limits, approximately 128 acres of the site was used for landfilling activities. According to Ref. #1 cited below, a geomembrane liner was installed below the greens.

PHASE 1 REPORT OVERVIEW

Ratcliffe Golf Services, Inc. retained SCS Engineers to conduct an initial assessment of the Renaissance Park Golf Course in support of a potential significant course renovation project. The focus of our Phase 1 work was to confirm the extent of impact of landfill-related settling on the golf course design and course operations, and outline a course of action to determine the impact that existing landfill disposal areas would have on any renovation project.

¹ Article titled "Garbage to Golf: Too Much Trash? Too Little Golf", Schmidt, Edward, Jr. (Golf Journal: Official Publication of the United States Golf Association, pp. 35-38; Jan-1991).

The Phase 1 Report (titled “Preliminary Evaluation and Engineering Assessment Renaissance Park Golf Course”, August 2017) provided a summary of our initial site assessment and discusses recommendations for addressing proposed improvements to golf course. The primary objective during Phase 1 was to develop an overall Existing Conditions Site Plan that depicts current site conditions overlaid on key golf course features and to gather information on the history of landfilling activities.

PHASE 2 REPORT OVERVIEW

SCS Engineers was retained to gather additional site-specific information regarding waste depths and waste limits, provide preliminary engineering and settlement analyses, and develop conceptual construction cost estimates for various options. These options included closing the golf course. Phase 2 assignments covered geotechnical and civil engineering evaluations to allow development of conceptual remedial designs that specifically address waste settlement (short and long term), stormwater management, and biogas management in landfilled areas.

Specific items covered during our Phase 2 assignments included the following:

- Preparation of a Work Plan that describes drilling activities to assess waste depth and limits of waste at critical locations, and general characteristics of the waste (appearance, moisture, degree of decomposition, composition).
- Subcontract with a drilling company to drill 17 boreholes.
- Update the Site Plan with new topography (provided by others).
- Develop a soil surcharge (preloading) approach to stabilize waste in certain areas, and associated costs and schedule for typical fairway remedial repair(s). Prepare memorandum with figures and standard details.
- Evaluate suitability and costs of other ground improvement methods including Rapid Impact Compaction (RIC), Deep Dynamic Compaction (DDC) and geopiers, and to develop preliminary cost estimates.
- Estimate landfill post closure costs if the golf course was closed instead of redeveloped.
- Develop preliminary construction costs estimates for soil surcharging, use of geogrids for soil fill placement, and installation of impervious flexible membrane liners (FML) for tees and greens to minimize the effects of methane gas.
- Provide recommendations for further investigations to support the golf course renovation design.
- Develop a preliminary Master Plan for potential redevelopment of the golf course, taking into consideration the current site conditions and potential mitigation steps necessary to address landfill-related issues. Ron Garl Golf Design headed the development of this Master Plan with input from SCS Engineers as well as JJKeegan+.
- A long-term financial evaluation of three proposed remediation strategies for the site, taking into consideration the estimated costs associated with each, the current revenue

realized at the course and projections of future income based on potential renovation work.

2 DRILLING PROGRAM

On December 4, 5, and 6, 2017 seventeen (17) borings were drilled at the site. SCS subcontracted SAEDACCO to conduct the drilling. A track mounted auger-type drill rig was used to advance 4-inch diameter hollow stem auger holes to measure waste depth and observe waste characteristics at key locations on the course/landfill. Prior to drilling, SCS prepared a Work Plan. A copy of the work Plan is included in **Appendix A**.

A site plan showing the boring locations, description of the waste encountered, and depth of boring is provided in **Appendix A**. Waste was encountered in twelve (12) of the 17 locations.

In general, the waste encountered appeared to be highly decomposed, wet, and lacking organic materials. This is indicative of mixed organic municipal solid waste (MSW) more than about 30 years old. Waste cuttings from the borings were collected and transported to the Republic Services' Charlotte Motor Speedway landfill in Concord, North Carolina for disposal in a lined permitted MSW landfill.

Prior to transporting the waste cuttings, samples were collected and shipped to Shealy Environmental Services, Inc. and testing per the requirements of Republic Services. The following tests were run on the waste cuttings:

- EPA Method 8260B – Toxicity Characteristic Leaching Potential (TCLP) Volatiles.
- EPA Method 8270D – TCLP Semi-volatiles
- EPA Method 8081B – TCLP Pesticides
- EPA Method 6010D – Metals
- EPA Method 8151A – TCLP Herbicides
- EPA Method 8082A – TCLP Polychlorinated biphenyl (PCB)

Copies of the analytical test results and disposal manifest are provided in **Appendix A**.

3 SOIL SURCHARGE ANALYSIS

OVERVIEW

Surcharging is widely used and reliable method of improving soft ground conditions, including for landfilled waste. The surcharge process involves placing several feet of soil across a surface or area to surcharge (pre-load) and compress the waste over time. The surcharge remains in place for a period of time (6 to 12 months, more or less) depending on the compressibility properties of the waste and the depth. The weight (height) of the soil surcharge is selected to be high enough to compresses the underlying soft soil or waste such that when the surcharge is removed, the potential for future settlement is within tolerable limits.

The height of the surcharge, and lateral extent, are functions of the proposed loads and tolerable rate and magnitude of future settlement. Typical guidance is for a surcharge loading (pressure) to be equal to 1.0 to 2.0 times the planned pressure of the new structure (load), depending on the type of structure and acceptable level of post-construction settlement. The surcharge remains in place until the rate of settlement is reduced to a magnitude deemed suitable for the structure.

An important advantage of surcharging over the other methods is that monitoring of settlement rates can be performed using basic survey methods and becomes an integral as part of the method. Monitoring allows the engineer to track the progress of settlement and make quantitatively based predictions as to when the surcharge may be removed and how much potential for settlement remains in the future. Typically, the initial rate and magnitude of surcharge-induced settlement will be relatively large; however, as time passes, the rate and magnitude will be reduced and eventually begin to level off. The disadvantage of surcharging is the time to complete the surcharge is not known until several sets of readings are available, and cost of bringing in and removing fill may be high in areas where fill is costly, or not readily available near the site.

TYPICAL SOIL SURCHARGE APPROACH

For executing a surcharge approach to stabilizing old landfilled areas, the following steps are recommended:

1. **Surcharge Area Delineation:** Delineate the physical limits of the surcharge area by field survey; place stakes or markers as needed to guide the earthwork contractor. In general, the outer edge of the surcharge (defined as the toe of the surcharge slope) should extend up to about 10 feet beyond the limits of the area designated for surcharging.
2. **Site Preparation:** Prepare the area selected for surcharge by installing silt fence as required by regulation, strip and grub surface vegetation including grasses, brush, trees and large roots that may be present. Stockpile stripped vegetation for subsequent reuse. If not removed, vegetative and organic materials will decompose and generate methane gas over time and create a potentially weak horizontal layer. The prepared surface area should be graded, and surface compacted to allow for drainage and as necessary to accommodate final design grades.
3. **Pre-Surcharge Survey and Settlement Plate Installations:** After the site limits have been established and site prepared, and before placement of surcharge material, the area should be surveyed for elevation and a topographic map prepared for the record. Settlement plates

should be placed at that time and it is critical that they be surveyed for location and elevation to establish baseline conditions.

See Figure 1 for a typical settlement plate detail. Both the bottom plate and top of the metal rod for each settlement plate should be surveyed at the beginning. After surcharging begins, only the top metal rod requires surveying. The selected surveyor should establish at least one elevation bench mark located completely off of the site and which will not be impacted by the surcharge or landfill settlement, and use that benchmark for all surveying. To the extent possible, the same survey crew and equipment also be used to minimize data noise.

The number and location of settlement places is shown on the design drawings. In general, a sufficient plate will be located within surcharged areas to allow for measurement of settlement (i.e., waste compression) over the full period of the surcharge, and allow for making future settlement predictions. It is important to anticipate that up to about half of the settlement plates may be damaged or destroyed by natural or man-made forces during the surcharge period, and the total number of plates installed should take that into account.




Figure 1. Typical Settlement Plate Details

4. **Surcharge Placement:** On-site stockpiled soil designated for surcharging shall be placed within the designated limits and to the desired thickness using conventional earthmoving equipment. Surcharge soil should primarily be inorganic, unsaturated, and unfrozen. As the lowermost one foot or more of the surcharge soil may remain in place and form part of the subgrade for future turf, tee boxes and green areas, special care should be taken to selecting suitable material. While compaction of the surcharge material is not essential, the material shall be placed in maximum 2 to 3 foot lifts so as to minimize the potential for voids

and to maximize the total weight of the surcharge. Field density testing is also not required, but the engineer and contractor should provide estimates of the weight of material placed.

5. **Settlement Plate Monitoring:** As noted in step 3, it is critical that each settlement plate be surveyed prior to placement of surcharge material to establish baseline conditions and that settlement plate readings be performed using the same equipment and methods from the beginning. Surveys should be performed to within 0.01 feet accuracy or about 1/8 inch. Readings should be taken at approximately the following intervals:
 - Initial (baseline) readings prior to placement of surcharge material
 - One to two weeks after completion of surcharge placement
 - Four weeks after completion of surcharge placement
 - Quarterly (12 week) intervals thereafter or until elevation change are within limits established by engineer.
6. **Settlement Plate Data Evaluation:** Survey information should be tabulated on a spreadsheet and provided to the engineer for evaluation. The information shall include the following:
 - Settlement plate number and coordinates (location)
 - Initial (baseline) elevation of base plate and top metal rod
 - Date of survey, weather, equipment and crew designation
 - Bench mark identification
 - Elevation of top of rod (base plate is covered up)
 - Comments (condition of settlement plate, distortion, damage, etc.)

During the surcharge period, the engineer will be evaluating the data and creating graphs depicting settlement versus time as shown on Figure 2.




Figure 2. Surcharge Settlement Monitoring Example

7. **Surcharge Removal:** Based on the trends of settlement, design goals and other factors, the engineer will prepare a report describing the results of the surcharging and recommendation for removal and regrading of the area.

CART PATHS

The existing cart paths at the course have been deteriorating for several years due to settlement and poor drainage. It is planned that new cart paths for the course renovation will be engineered to minimize the effects of settlement. The following three options have been identified for stabilizing the subsurface for the new cart paths:

- Rapid Impact Compaction (RIC)
- Soil Surcharge
- Standard compaction equipment

Stabilizing the subsurface should cause settlement of 2 to 3 feet. Engineered fill will be placed and compacted and the use of geogrids will be explored (in Phase 3) to help spread the cart path loads. It is also possible that localized areas will require waste removal to further aid in stabilizing the subsurface. Further evaluation for cart paths will be explored during the final engineering and design phase.

4 SOIL STOCKPILE ASSESSMENT

The soil stockpile, which was placed between 2013 and 2014, is located west of Hole No. 5 alongside Sugar Creek. As stated above, the stock pile contains approximately 240,000 cubic yards of soil. The footprint of the stockpile is about 15 acres and is situated over landfilled areas.

During our site reconnaissance, SCS personnel examined portions of the stockpile. Overall, there is a good vegetative cover that includes young poplar trees, brush, and woody plants. The top area and slopes were viewed and overall the condition of the vegetative cover was suitable and surface erosion was minimal. The terraces on the northwest side of the stockpile appear intact, did not exhibit obvious signs of instability, and storm water pipes were in-place. The southern toe of slope, which is heavily vegetated, was also examined. There were no obvious signs of slope instability, sloughing, excess erosion, exposed waste, or landfill leachate seepage.

The overall slope of the stockpile sides range from 4 horizontal to 1 vertical (4H:1V) to 2.2H:1V. Slopes between terraces on the west side are in the 1.5H:1V. Although the slopes appear steep, the addition of the terraces flatten out the overall slope. These slopes are similar to those at the end of the driving range which have been in place for years.

SCS recommends removing some of the soil from the stockpile to flatten the overall slope to a 3H:1V range. Furthermore, a slope stability analysis should be performed during the Phase 3 engineering evaluations.

In addition to the site reconnaissance, SCS reviewed historical data from groundwater monitoring wells in the vicinity of the soil stockpile before and after the soil stockpile was placed (*Semi-Annual Monitoring Report, First Half 2018, Former York Road Landfill, Geosyntec, May 2018*). The groundwater wells reviewed included: YRW-10C, DDW-01, DDW-01A, DDW-02. Based on our review, the placement of the soil stockpile caused no impact to groundwater quality. We also reviewed the four methane gas probes in the vicinity of the soil stockpile (#32, 33, 34, and 35). Methane gas was not detected in any of these probes.

The material in the stockpile is an asset and should be used for filling and grading when mitigating the landfill settlement issues. Based on the information reviewed to date, there appears to be no adverse conditions caused by the soil stockpile.

5 PERMITTING REQUIREMENTS

The York Road Landfill was closed in 1987 according to available records. The City of Charlotte, which owns the landfill, is responsible for environmental monitoring (groundwater, methane gas migration, and cover integrity) at the landfill.

The following notifications should be made prior to any construction at the site:

- Notify the City of Charlotte, Environmental & Property Management. Since the City of Charlotte is the owner of the landfill all permit applications and agency notifications should be reviewed by the City.
- North Carolina Department of Environmental Quality (NCDEQ), Energy, Mineral and Land Resources, Mooresville office for Erosion and Sediment Control permitting.
- North Carolina Department of Environmental Quality (NCDEQ), Solid Waste Section, Asheville office.

SCS recommends coordinating all agency notifications with the City of Charlotte. Furthermore, we recommend meeting with NCDEQ early during the Phase 3 portion of the project to present the overall concept and discuss permitting strategies.

6 PROPOSED GOLF COURSE RENOVATION BY RON GARL GOLF DESIGN

OVERVIEW

Ron Garl Golf Design was tasked with developing a Master Plan along with refining preliminary cost estimates for both a nine-hole renovation and eighteen-hole renovation. This project presented unique challenges in that it not only needed to address design elements that would make the golf course more appealing to the market it served, it needed to simultaneously address the specific landfill settling issues that have decimated the existing golf course.

The first step in this process was to develop a concept or overriding theme of the course that provided an experience that fulfilled the recommendations outlined in the study provided by JJKeegan+. Once that was defined, design work began on the overall Master Plan by focusing on specific holes for particular areas of the property. These holes needed to be carefully researched and designed in order to accommodate the existing topography as well as possible, while providing the opportunity to increase fill to accommodate the soil surcharge and removal with the least amount of time and expense. The final result is a unique and extremely promising golf course design that will have a wide appeal to the golfing public, and not only greatly improve the golfer experience, but contribute to the overall community and image of Charlotte and Mecklenburg County as well.

COURSE DESIGN – THE THEME: THE JOURNEY WITH HARRY L. JONES, SR. GOLF COURSE

Ron Garl has designed over 250 golf courses around the world, and has an industry wide reputation for building facilities that garner unique attention and wide-spread accolades. Tiger Wood's first win on the PGA Tour was at a Ron Garl design, as was his first International win. In analyzing the opportunity at the Harry L. Jones, Sr. Golf Course, Ron immediately recognized his challenge; he said "When a golfer comes to Charlotte, they currently say 'I wish I could play at the Quail Hollow Club'. When we get through with this course, they will say 'I wish I could play at the Harry L. Jones, Sr. Golf Course.'"

Fulfilling that goal in the design process required a multi-pronged approach. First, in response to the market research conducted by JJKeegan+, the course design was softened to make it more appealing to a wide range of golfers. Forced carries (which require a golfer to hit a shot over an obstacle such as a creek or lake) were removed as much as possible. Holes were shortened. Blind shots were removed.

Secondly, an overall theme was adopted in the design which focused on creating a *golf experience* rather than just providing a golf course to play. This went so far as to propose a slight alteration in the name of the facility, to The Journey with Harry L. Jones, Sr. Golf Course. In the new design, a golfer will not just be playing a golf course – they will be embarking on a Journey through golf course history and design, hosted by Harry L. Jones. This unique approach has never been done in this manner, and has an incredible appeal to golfers of all skill levels.

The underlying principle of this theme is that every hole tells a story. It may be inspired by a famous Golf Course Architect or one of his holes or a famous shot or a famous design feature that has been successfully used in the past. As the golfer plays the course, they learn about these stories, about

even about their own approach to the game of golf. The story of each hole is conveyed through as many as five elements:

The Five Elements

- 1. STORY.** There will be a plaque at the beginning of each hole which describes the story (famous golf hole, architect's style or distinctive design feature) that is presented on that hole.
- 2. POINT OF INTEREST.** Each hole will have additional points of interest (some may have more than one) that we want to explain to the golfer. These will often be much smaller plaques or signage. In some instances they may link through QR code to online videos describing the Point of Interest in more detail.
- 3. STRATEGY.** Many golf courses have "Tips from the Pro" of the course on how to play the hole. We will have a wide variety of people – from PGA Professionals to Golf Course Architects to "Harry Jones" himself – provide tips on how to implement strategy for playing each hole.
- 4. CONSTRUCTION.** During the construction of the course, we are going to take extensive videos and pictures of the work. These will be used to tell the story of how the course was built – both in signage and videos.
- 5. THE SHOT.** Many of the holes we are using are not only famous in themselves, but they are known for a particular shot that was made during a golf event. For these, we will have plaques/signage commemorating that particular shot – and inviting the golfer to attempt that particular shot themselves to see if they are able to recreate it.

THE DESIGN – THE MASTER PLAN

Once the theme was established, the task of designing a course that incorporated the five story elements into each hole began. This required hundreds of hours of research to find the right fit for each particular hole. First, the hole needed to fit within the overall routing plan for the property, as well as being suitable for the topography that existed before and after addressing the landfill settling issues. The hole needed to be significant enough in golf history to accommodate the five elements of the story. Ultimately one of the most critical considerations was making sure the hole would be a popular, fun hole for golfers to play.

The resultant Master Plan achieves the objectives set out in the initial meetings. It is a unique blend of holes with historically significant inspirations that will entertain golfers as well as inform them on a variety of topics that they probably did not fully understand. By using the five elements to tell the story, and basing each hole on an inspiration from a significant hole, person or even famous shot made in golf, the Journey with Harry L. Jones, Sr. Golf Course will be a "must play" golf course for every golfer in Charlotte, as well as those that travel to this area.

Appendix B. – Master Plan for The Journey with Harry L. Jones, Sr. Golf Course

7 COST ESTIMATES

GOLF COURSE CLOSURE

A cost estimate was prepared by SCS to address the long-term post-closure activities associated with the landfill if the golf course was closed. The post-closure cost estimate includes mowing, cover restoration, and reseeded. The cost for groundwater and methane probe monitoring were not included in this cost estimate since the City is required to conduct these regardless of the course status. The post-closure cost estimate is provided in **Appendix C, Attachment C-1**.

GOLF COURSE RENOVATION COST ESTIMATE

Two preliminary construction cost estimates were prepared to address the full 18-hole renovation of the golf course. Preliminary costs related to the golf course renovation (tees, greens, cart paths, irrigation system, grassing, bunkers, etc.) were prepared by Ron Garl Golf Design. This estimate is provided in **Appendix C, Attachment C-2**.

Cost related to the engineering challenges for the course renovation where prepared by SCS Engineers. These costs include, but not limited to, the following:

- RIC for portions of the cart paths to improve subsurface conditions
- Synthetic liners under tees and greens to protect from methane gas intrusion
- Soil surcharging to improve subsurface conditions.
- Surveying and monitoring of the soil surcharges during construction
- Geogrid reinforcement for cart path to improve stability and reduce differential settlement

The cost estimates along with key assumptions are provided in **Appendix C, Attachment C-3**.

Both construction cost estimates will be refined/updated during the development of the Final Construction Drawings and Specifications (Phase 3).

8 FINANCIAL PROJECTIONS AND FEASIBILITY ANALYSIS

OVERVIEW

JJKeegan+ was retained to perform an in-depth study of the Harry L. Jones, Sr. Golf Course operation, including a market evaluation of each of three possible courses of action regarding the property.

Utilizing a state-of-the-art analytic approach to demographics within a 10-mile radius of the property, JJKeegan+ founder Jim Keegan used cost estimates provided by SCS Engineers and Ron Garl Golf Design to analyze the potential return on investment of each proposed remedy.

The analysis included a site visit by Mr. Keegan, coupled with an extensive comparative market review where he visited the courses throughout the area considered to be competitors of the Harry L. Jones, Sr. Golf Course.

Mr. Keegan then conducted a Golfer Local Market Analysis utilizing the Mosaic profile of demographics within a 10-mile radius of the facility. These metrics yielded not only an extensive insight into the current demand for golf that exists in the study area, they provided guidance for the type of golf course that should be built in order to appeal to the widest range of potential customers in proximity to the course. This information was shared with Ron Garl Golf Design, who in turn incorporated the suggestions from Mr. Keegan's study into the Master Plan for the course.

For the financial return analysis, Mr. Keegan took into account the projected cost of each option and performed a study to determine the return on investment of each option. In the scenario where the course retained 9 holes and, in the scenario, where the course remained an 18 hole facility, he utilized existing revenue numbers and applied projections based on existing GLMA data, corrected for the suggested course improvements identified in the Mosaic profile analysis.

ANALYSIS: OPTION 1, CLOSE THE COURSE

The first potential course of action would be to simply close the course and allow the property to revert to the status of a closed landfill. This option entails certain one-time expenses of closure, and an annual maintenance of the property to meet post-closure permitting requirements. The financial analysis of this option was fairly straight-forward, requiring a totaling of expenses over the 30-year projected study period. The initial cost of preparing the course (\$150,000), combined with the annual cost of maintenance over the 30-year period (\$2,900,000) resulted in a net present-day loss of \$1,777,280.

Just Closing the Landfill Makes No Sense

| | |
|-----------------------------------|--------------|
| Total Input Capital | -\$150,000 |
| Accumulated Annual Return/Expense | -\$2,900,000 |
| Total Return | -\$3,050,000 |
| IRR | negative |
| Net Present Value | -\$1,777,280 |

ANALYSIS: OPTION 2, CLOSE 9 HOLES, RENOVATE THE REMAINING 9 HOLES

The first nine holes, as well as a portion of the 10th and 18th holes, are on the former landfill. Thus, the bulk of the “back” nine (holes 10 through 18) are not on landfill. Thus, it is possible to mitigate further issues related to landfill settling by closing the front nine and renovating the second nine into a course consisting of only nine holes.

Mr. Keegan determined that this course of action would result in a slightly better return over the course of the study period, but there is one variable that could make the 9-hole renovation less appealing than simply closing the entire facility: the continued maintenance of the landfill portion of the property.

While some expenses of closing the landfill holes could be mitigated during the renovation of the back nine (for example, the need to decommission the irrigation would supposedly be handled in the new irrigation system installation), the ongoing expense of maintenance of the closed holes would present some type of recurring expense. This was not factored in due to the unknown nature of that expense, and how it would be handled in conjunction with the maintenance of the remaining 9 holes.

The financial analysis of this option resulted in a total net return over the 30-year period of \$3,642,949, representing a net present-day value of \$199,625.

The Nine Hole Generates Positive Net Present Value But Doesn't Maximize Investment Return

| | Close Landfill | 9-Hole |
|--|----------------|--------------|
| Total Input Capital | -\$150,000 | -\$3,732,237 |
| Accumulated Annual Return/Expense | -\$2,900,000 | \$7,375,186 |
| Total Return | -\$3,050,000 | \$3,642,949 |
| IRR | negative | 1.16% |
| Net Present Value | -\$1,777,280 | \$199,625 |

ANALYSIS: OPTION 3, RENOVATE ALL 18 HOLES

The third and final option for addressing the issues facing the Harry L. Jones Golf Course is a complete renovation of all 18 holes. This process would entail addressing the existing conditions found on the landfill/golf course and providing for engineering and design solutions that would mitigate, offset or otherwise reduce the risk of future impacts due to landfill related settling and other issues resulting from having a public golf operation on a landfill.

Mr. Keegan utilized an array of tools he has developed to determine the potential revenue of the facility and extrapolated that out over the 30-year study period utilized in the analysis of the other options. Using the projected preliminary construction expense numbers from the Phase I study, he calculated that the total return over the study period would be \$6,155,401. The resultant Net Present Value of the 18-hole renovation option was \$606,513, leading to his conclusion that the renovation of the entire golf course was the most viable option from a financial analysis standpoint.

It is important to note that this analysis does not include any projections or considerations of the economic impact to the area if the amenity that the golf course represents to this community were to close and no longer be available for public use.

Renovating the 18-hole Golf Course Is Most Viable Option

| | Close Landfill | 9-Hole | 18-Hole |
|--|----------------|--------------|--------------|
| Total Input Capital | -\$150,000 | -\$3,732,237 | -\$5,694,109 |
| Accumulated Annual Return/Expense | -\$2,900,000 | \$7,375,186 | \$11,849,510 |
| Total Return | -\$3,050,000 | \$3,642,949 | \$6,115,401 |
| IRR | negative | 1.16% | 1.64% |
| Net Present Value | -\$1,777,280 | \$199,625 | \$606,513 |

9 CONCLUSION AND NEXT STEPS – PHASE III

It is the unanimous conclusion of the consultants that are a party to this report that action should be taken to remediate the problems at the Harry L. Jones Golf Course. In the current state, the impact of landfill settlement have rendered the golf course difficult to maintain to any reasonable standards. Secondary impacts caused by settlement affect drainage and irrigation of the golf course, which are further accelerating the settling of the landfill. Ponding water and other issues threaten the compliance with the closed landfill permit, and some areas of the property with direct access and exposure to the golfers present significant safety risk issues. If nothing is done, it is only a matter of time before an incident occurs that could result in serious injury to a user of the facility.

The study of potential corrective action for the Harry L. Jones Golf Course was originally intended as a five-phase process. This report concludes Phase II of that process, and at this point the project is yielding the desired objective, which was a refined, well-informed decision path for next steps.

Of the three potential options, the studies have indicated that the best course of action is to renovate the entire golf course. This not only is the best decision from the financial perspective of this specific property, there are intrinsic, passive benefits to the neighboring community as well. Allowing the property to revert to a static landfill will have a profound effect on the region surrounding the golf course. On the other hand, investing in a revitalization that promises to turn the current asset, which has a distinctly negative stigma, into a popular, well-perceived amenity to the area has immeasurable benefits.

It is the recommendation of this Phase II report that the governing bodies move to implement Phase III of the process, which is to develop working documents including Construction Drawings, Specifications and permitting for the renovation of the entire golf course. This phase would include finalizing the engineering, design, and procurement process to select a contractor or contractors to complete the renovation. The estimated timeline for Phase III would be approximately 9 months.

Phase IV, which would include actual construction, field engineering and construction administration, is expected to take approximately 24 months for completion.

The final step, Phase V, would entail post-construction maintenance and monitoring. In this phase, a Maintenance and Monitoring Plan would be developed. This Plan will establish inspection guidelines and procedures to ensure early detection and repair of problems caused by landfill settling. Phase V activities would be implemented throughout the life of the facility. Initially, it is anticipated that minimal output would be required to implement Phase V. However, long-term maintenance activities and repairs due to landfill settling are hard to predict at this time.

Appendix A

Work Plan Subsurface Investigation



**Work Plan
Subsurface Investigation
Harry L. Jones, Sr. Golf Course**

Presented to:

Ratcliffe Golf Services, Inc.



800 Radio Road
Charlotte, NC 28216

Presented by:

SCS ENGINEERS, PC
2520 Whitehall Park Road, Suite 450
Charlotte NC, 28273

October 25, 2017
File No. 02217302.01

Offices Nationwide
www.scsengineers.com

SCS ENGINEERS, PC

October 25, 2017
File No. 02217302.01

Mr. David Wolfe, P.E., ENV SP
Program Manager
Environmental Services
Engineering & Property Management
Charlotte, NC

Mr. Joseph S. Hack, QEP
Solid Waste Management
Mecklenburg County
2145 Suttle Avenue
Charlotte, NC 28208


Subject: Work Plan for Subsurface Investigation
Harry L. Jones, Sr. Golf Course

Dear Mr. Wolfe and Mr. Hack:

On behalf of Ratcliffe Golf Services, SCS Engineers present this Work Plan for the planned subsurface investigation at the Harry L. Jones, Sr. Golf Course. Our subsurface investigation includes borings and test pits to help define the depth and location of buried municipal solid waste at the course.

If you have any questions or require any additional information, please contact me at 704-504-3107 or at slamb@scsengineers.com.

Sincerely,



Steven C. Lamb, PE
Vice President
SCS ENGINEERS, PC



Robert H. Isenberg, PE, CPG
Senior Vice President
SCS ENGINEERS, PC

scl/rhi

cc: Del Ratcliffe, Harry L. Jones, Sr. Golf Course
Larry Frost, NCDEQ

Enclosures



**Work Plan
Subsurface Investigation
Harry L. Jones, Sr. Golf Course**

Presented To:

Ratcliffe Golf Services, Inc.
800 Radio Road
Charlotte, NC 28216

Presented From:

SCS ENGINEERS, PC
2520 Whitehall Park Drive, Suite 450
Charlotte, NC 28273

October 25, 2017
File No. 02217302.00

Table of Contents

| Section | Page |
|---|------|
| 1.0 INTRODUCTION AND BACKGROUND..... | 1 |
| 2.0 SITE CONDITIONS..... | 1 |
| 3.0 DRILLING AND TEST PIT PROGRAM | 1 |
| 4.0 HEALTH AND SAFETY | 2 |
| 5.0 PERMITTING..... | 3 |

Figures

| No. | |
|-----|----------------------|
| 1 | Boring Location Plan |

1.0 INTRODUCTION AND BACKGROUND

The Harry L. Jones, Sr. Golf Course (formerly known as the Renaissance Park Golf Course) is located at 1525 West Tyvola Road in Charlotte North Carolina. The course is owned by the City of Charlotte (City) and managed by the Mecklenburg County Parks and Recreation Department (MCPR). Prior to redevelopment of the property as a golf course, the site was a municipal solid waste disposal facility known as the York Road Landfill.

Ratcliffe Golf Services, Inc. retained SCS Engineers to conduct an assessment of the course in support of a potential significant course renovation project. The assessment focused on the impact that existing landfill disposal areas would have on a renovation project. Phase 1 engineering assignments, which addressed overall conditions of the golf course, were completed earlier this year. Upcoming Phase 2 assignments include obtaining additional site-specific information regarding waste depths and waste limits in areas underlying tee boxes, fairways, greens and cart paths, as well as providing preliminary engineering and settlement analyses, and developing conceptual construction cost estimates for various remedial options.

This Work Plan describes the procedures to be followed during the field investigation activities under Phase 2 to establish depth of waste and waste limits at select locations.

2.0 SITE CONDITIONS

Harry L. Jones, Sr. Golf Course is situated on approximately 300 acres. The course is an 18 hole municipal golf course with a driving range and a par 3 learning center. Portions of the golf course are situated over top of the York Road Landfill, a closed municipal solid waste disposal facility.

SCS is coordinating our subsurface investigative work with Ratcliffe and Ron Garl Golf.

3.0 DRILLING AND TEST PIT PROGRAM

SCS will subcontract with a licensed drilling contractor to drill between 15 and 20 boreholes in pre-selected locations at the course. The boring locations were selected by Ratcliffe Golf, Ron Garl Golf and SCS Engineers and illustrated on **Figure 1**.

SCS Engineers personnel will field locate and stake all boring locations. A truck mounted rotary drill rig (or similar) will be used to auger and sample boreholes to the various depths as indicated below:

- Where waste is encountered, boring will extend 2 to 3 feet below the bottom of waste, into native soil.
- If no waste is encountered, borings will be up to 20 feet deep maximum.
- Per ASTM D1586, Standard penetration test (SPT) sampling and blow counts (N-values) will be performed at 5 to 10 foot depth intervals for select borings. Samples will be

inspected for moisture content, degree of decomposition and composition, both useful for evaluating future settlement. If hard or large obstructions are encountered, the sampling frequency or depth ranges may be amended.

Borings will be logged by the driller for types of materials encountered, depth of liquids, and other conditions, under observations of a representative of SCS Engineers. Soil drill cuttings may be disposed on site, but waste drill cuttings will need to be drummed separately, tested for presence of hazardous materials, and properly disposed of at the Republic Services Charlotte Motor Speedway Landfill in Concord. Records of testing and disposal will be maintained by SCS and provided to the City and County upon request.

All borings will be backfilled with a heavy bentonite slurry, or with bentonite pellets, up to 2 feet below ground surface. The final 2 feet of the borehole will be backfilled with clean, inorganic soil and the final surface of all disturbed area will be seeded or sodded by Ratcliffe Golf, as necessary to support vegetative growth.

Following the drilling program, or during, it is proposed to excavate test pits (and/or Geoprobe boreholes) at select locations to delineate the edge of waste, or waste boundary. Test pits will be excavated with a backhoe, excavator, or similar equipment that can reach depths of up to 6 to 8 feet. Test pits will be monitored and logged by SCS. All material excavated will be placed back into the test pit and compacted with the backhoe bucket. Just as for the borings, the final 2 feet will be backfilled with clean soil, compacted, and the surface restored.

All borings and test pit locations will be field surveyed for horizontal location (N/S and E/W coordinates) and mean sea level elevation. A final report will be prepared by SCS Engineers, following the completion of the field work. The final report will include a narrative of activities, summary of findings, boring and test pits logs, survey data, site plan, lab data and photographs.

4.0 HEALTH AND SAFETY

Drilling and test pitting work will occur within or in close proximity to municipal solid waste and within a zone of potential health and safety issues including methane and H₂S gas emissions, leachate, organic and metallic waste and other disposed materials.

The Driller is responsible for site health and safety for its own employees and shall prepare a Site Health and Safety Plan, and provide a copy of this Plan to SCS Engineers for informational purposes only. The Site Health and Safety Plan shall be prepared in accordance with applicable provisions of OSHA regulations 29 CFR 1910.120 and 1926.


Prior to any drilling or test pit excavation, a tailgate safety meeting will be conducted at the course. Personal protective equipment (PPE) shall include hard hat, hearing protection, and safety boots. SCS will also have a gas meter to monitor atmosphere in the working zone.

5.0 PERMITTING

SCS Engineers reviewed of the City of Charlotte Erosion Control Requirements. The amount of land to be disturbed is less than one acre, therefore an erosion and sedimentation plan is not required. However, all efforts will be used to limit erosion during the subsurface exploration activities. In general, all boreholes and test pits will be backfilled immediately following their development. All disturbed areas will be re-seeded as needed.

SCS Engineers contacted Mr. Larry Frost, NCDEQ, Waste Management Solid Waste Section Permitting Branch and inquired about any permits or notifications that are required prior to drilling. Mr. Frost stated a permit from NCDEQ is not needed, however, they would like to review this Work Plan. A copy of this Work Plan was submitted to NCDEQ.

M:\CAD\PROJECT DRAWINGS\02212302.00 - Remediation Plan GC Design\Henry L. Jones, SCS Boring Plan\SH01-HLJ_S01_BORING PLAN.dwg Oct 24, 2017 - 12:35pm Layout Name: Layout1 By: 4281J.L.




LEGEND

- 2-FOOT CONTOUR
- 10-FOOT CONTOUR
- WASTE LIMITS
- TREELINE
- STREAM
- 100-YR FLOOD PLAIN LIMITS
- TRANSMISSION TOWER
- POWER POLE
- TB#** - TEE BOX
- F#** - FAIRWAY
- G#** - GREEN
- SB-# (25')** - SOIL BORING (EST. DEPTH)

| | | |
|----------------------------------|----------------|--|
| TEST BORING LOCATION PLAN | | RATCLIFFE GOLF SERVICES, INC. 800 RADIO ROAD CHARLOTTE, NC 28216 |
| NO. | REVISION | DATE |
| | | |
| | | |
| SHEET TITLE | | PROJECT TITLE |
| TEST BORING LOCATION PLAN | | HARRY L. JONES, SR GOLF COURSE SITE ASSESSMENT |
| CLIENT | | SCS ENGINEERS, PC 2520 WHITEHALL PARK DRIVE, SUITE 450 CHARLOTTE, NORTH CAROLINA 28273 PHONE: (704) 504-3107 FAX: (704) 504-3174 |
| CADD FILE: | SHT01-HLJ... | |
| DATE: | OCTOBER 2017 | |
| SCALE: | AS SHOWN | |
| DRAWING NO. | 01 of 1 | |

Soil Boring Results and Site Plan

M:\CADD PROJECT DRAWINGS\2217302.00 - Renaissance Park GC Design\HLJ - SITE PLAN V0.1.dwg Oct 02, 2018 - 1:03pm Layout Name: HLJ-SITE PLAN (ARCH E) By: 4281-L



| HARRY L. JONES GOLF COURSE | | | | | | | |
|----------------------------|----------|-----------|-----------------|--|--------------------------|-------------------------|--------------------------------|
| TEST BORING RESULTS | | | | | | | |
| DECEMBER 4th - 6th, 2017 | | | | | | | |
| BOREHOLE | NORTHING | EASTING | ELEVATION (ft.) | LOCATION | TOTAL BORING DEPTH (ft.) | DEPTH OF SOIL CAP (ft.) | DEPTH TO BOTTOM OF WASTE (ft.) |
| SB-1 | 525,002 | 1,427,343 | 560 | Hole #14 Fairway | NA | NA | NA |
| SB-2 | 525,113 | 1,427,441 | 568 | Hole #14 Fairway | NA | NA | NA |
| SB-3 | 524,910 | 1,428,717 | 553 | Hole #18 Fairway | 35 | 35 | NA |
| SB-4 | 524,813 | 1,428,845 | 562 | Adjacent to Hole #18 Fairway (Tyvola Side) | 45 | 6 | 42 |
| SB-5 | 523,745 | 1,428,067 | 565 | Hole #10 Fairway | 15 | 15 | NA |
| SB-6 | 523,732 | 1,428,330 | 561 | Between Fairway and Tee Box Hole #10 | 15 | 15 | NA |
| SB-7 | 523,205 | 1,429,340 | 549 | Hole #9 Fairway | 50 | 5 | 50 |
| SB-8 | 522,749 | 1,430,014 | 529 | Hole #1 Fairway | 25 | 5 | 24 |
| SB-9 | 522,714 | 1,430,050 | 534 | Hole #1 Fairway | 32 | 2 | 32 |
| SB-10 | 522,702 | 1,430,103 | 531 | Hole #1 Fairway | 27 | 5 | 27 |
| SB-11 | 522,740 | 1,430,147 | 539 | Adjacent to Hole #1 Fairway (Tyvola Side) | 25 | 25 | NA |
| SB-12 | 522,199 | 1,430,339 | 559 | Behind Green Hole #1 | 40 | 10 | 40 |
| SB-13 | 522,166 | 1,429,939 | 543 | Hole #8 Fairway | 42 | 6 | 42 |
| SB-14 | 521,982 | 1,429,766 | 540 | Hole #8 Fairway | 40 | 2 | 32 |
| SB-15 | 521,336 | 1,429,447 | 527 | Behind Green Hole #2 | 42 | 10 | 42 |
| SB-16 | 521,624 | 1,429,795 | 543 | Hole #2 Fairway | 40 | 4 | 23 |
| SB-17 | 521,635 | 1,428,602 | 503 | Hole #7 Fairway | 25 | 25 | NA |
| SB-18 | 522,569 | 1,427,895 | 545 | Hole #6 Fairway | 47 | 5 | 47 |
| SB-19 | 521,640 | 1,428,233 | 519 | Hole #4 Fairway | 41 | 2 | 39 |

| LEGEND | |
|--------|---------------------------|
| | 2-FOOT CONTOUR |
| | 10-FOOT CONTOUR |
| | WASTE LIMITS |
| | STREAM |
| | TRANSMISSION TOWER |
| | POWER POLE |
| | GROUNDWATER WELL |
| | METHANE PROBE |
| | SOIL BORING (BORED DEPTH) |

NOTES:
 BASE SOURCE MAP: LANDFILL SURFACE GRADES TAKEN FROM

| | |
|--|----------|
| NO. | DATE |
| | REVISION |
| SHEET TITLE | |
| PROJECT TITLE | |
| HARRY L. JONES GOLF COURSE | |
| CLIENT | |
| RATCLIFFE GOLF SERVICES 800 RADIO ROAD CHARLOTTE, NORTH CAROLINA 28216 | |
| CADD FILE: | |
| DATE: | |
| AUGUST | |
| SCALE: | |
| AS SHOWN | |
| DRAWING NO. | |
| 01 of | |

SCS ENGINEERS, PC
 2820 WHITEHALL PARK DRIVE, SUITE 400
 CHARLOTTE, NC 28216
 PHONE: (704) 584-3107 FAX: (704) 584-3174

HARRY L. JONES GOLF COURSE

TEST BORING RESULTS

DECEMBER 4th - 6th, 2017

| BOREHOLE | NORTHING | EASTING | ELEVATION (ft.) | LOCATION | TOTAL BORING DEPTH (ft.) | DEPTH OF SOIL CAP (ft.) | DEPTH TO BOTTOM OF WASTE (ft.) | WASTE DESCRIPTION (MOISTURE, ODOR, TEXTURE) |
|----------|----------|-----------|-----------------|--|--------------------------|-------------------------|--------------------------------|---|
| SB-1 | 525,002 | 1,427,343 | 560 | Hole #14 Fairway | NA | NA | NA | |
| SB-2 | 525,113 | 1,427,441 | 568 | Hole #14 Fairway | NA | NA | NA | |
| SB-3 | 524,910 | 1,428,717 | 553 | Hole #18 Fairway | 35 | 35 | NA | |
| SB-4 | 524,813 | 1,428,845 | 562 | Adjacent to Hole #18 Fairway (Tyvola Side) | 45 | 6 | 42 | 6'-22': mostly plastic netting, paper, wood debris, rubber, indiscernibles 22'-30': greyish indiscernible material, paper, plastics, rubber 30'-42': greyish indiscernible material, plastics, fabric 42'-45': little moist, greyish soil (NO WASTE) (Smelled like active face) |
| SB-5 | 523,745 | 1,428,067 | 565 | Hole #10 Fairway | 15 | 15 | NA | |
| SB-6 | 523,732 | 1,428,330 | 561 | Between Fairway and Tee Box Hole #10 | 15 | 15 | NA | |
| SB-7 | 523,205 | 1,429,340 | 549 | Hole #9 Fairway | 50 | 5 | 50 | 5'-16': soil, plastics, rubber, wire, greyish indiscernibles 16'-21': moist soil, plastics, greyish indiscernibles 21'-50': wet "soupy" greyish/brown indiscernibles, plastics (NEVER OUT OF WASTE) |
| SB-8 | 522,749 | 1,430,014 | 529 | Hole #1 Fairway | 25 | 5 | 24 | 5'-8': greyish soil, plastics, fabric 8'-20': moist fabric, plastics, rubber hose 20'-24': wet greyish soil/indiscernibles, few plastics 24'-25': wet greyish soil (NO WASTE) |
| SB-9 | 522,714 | 1,430,050 | 534 | Hole #1 Fairway | 32 | 2 | 32 | 2'-15': wet grey soil, roots, some waste 15'-16': refusal at 16'; wet msw (roofing mat) 16'-32': wet msw, soil (NEVER OUT OF WASTE) |
| SB-10 | 522,702 | 1,430,103 | 531 | Hole #1 Fairway | 27 | 5 | 27 | 5': msw 10'-13': wet soil 13'-18': moist black msw 22'-27': wet msw mixed with soil (NEVER OUT OF WASTE) |
| SB-11 | 522,740 | 1,430,147 | 539 | Adjacent to Hole #1 Fairway (Tyvola Side) | 25 | 25 | NA | |
| SB-12 | 522,199 | 1,430,339 | 559 | Behind Green Hole #1 | 40 | 10 | 40 | 10'-30': moist soil, indiscernibles, mostly fabric 30'-40': wet soil, indiscernibles, fabric (NEVER OUT OF WASTE) |

HARRY L. JONES GOLF COURSE

TEST BORING RESULTS

DECEMBER 4th - 6th, 2017

| BOREHOLE | NORTHING | EASTING | ELEVATION (ft.) | LOCATION | TOTAL BORING DEPTH (ft.) | DEPTH OF SOIL CAP (ft.) | DEPTH TO BOTTOM OF WASTE (ft.) | WASTE DESCRIPTION (MOISTURE, ODOR, TEXTURE) |
|----------|----------|-----------|-----------------|----------------------|--------------------------|-------------------------|--------------------------------|---|
| SB-13 | 522,166 | 1,429,939 | 543 | Hole #8 Fairway | 42 | 6 | 42 | 6'-12': few wood, plastics, greyish/brown indiscernibles 12'-27': wet "soupy" indiscernible material, plastics 27'-42': moist/"pasty" grey indiscernible material, plastics, wire (NEVER OUT OF WASTE) |
| SB-14 | 521,982 | 1,429,766 | 540 | Hole #8 Fairway | 40 | 2 | 32 | 2'-16': greyish/black indiscernible material, plastics, wood material 16'-32': greyish/black "soupy" material, few plastics 32'-40': soil, moist to wet (NO WASTE) |
| SB-15 | 521,336 | 1,429,447 | 527 | Behind Green Hole #2 | 42 | 10 | 42 | 10'-12': soil, plastics, indiscernibles 12'-42': wet "soupy" brownish soil/indiscernible material, plastics, fabric (NEVER OUT OF WASTE) |
| SB-16 | 521,624 | 1,429,795 | 543 | Hole #2 Fairway | 40 | 4 | 23 | 4'-13': plastics, few wood chips, mostly greyish soil/indiscernible material 13'-23': few plastics, mostly soil & indiscernible material 23'-40': soil, around 35' soil little moist, (NO WASTE) |
| SB-17 | 521,635 | 1,428,602 | 503 | Hole #7 Fairway | 25 | 25 | NA | |
| SB-18 | 522,569 | 1,427,895 | 545 | Hole #6 Fairway | 47 | 5 | 47 | 5'-8': soil, plastics, cable, indiscernibles 8'-47': wet "soupy" greyish/indiscernible material, plastics, fabric, wire (NEVER OUT OF WASTE) |
| SB-19 | 521,640 | 1,428,233 | 519 | Hole #4 Fairway | 41 | 2 | 39 | 2'-15': soil, greyish indiscernibles, plastics, fabric, rubber 15'-39': wet greyish "soupy" indiscernible material, few plastics 39'-41': wet "soupy" material (refusal) (Faint msw/lfg smell) |

Waste Cutting Disposal and Lab Results

Report of Analysis

SCS Engineers
2520 Whitehall Park Drive #450
Charlotte, NC 28273
Attention: Steve Lamb

Project Name: Ratcliff E. Golf, REN. PARK GC DESIGN

Project Number: 02217302.00

Lot Number: **TB08087**

Date Completed: 02/20/2018

N. Saikaly

02/28/2018 12:16 PM
Approved and released by:
Project Manager: Nisreen Saikaly



The electronic signature above is the equivalent of a handwritten signature.
This report shall not be reproduced, except in its entirety, without the written approval of Shealy Environmental Services, Inc.

SHEALY ENVIRONMENTAL SERVICES, INC.

SC DHEC No: 32010001

NELAC No: E87653

NC DENR No: 329

NC Field Parameters No: 5639

Case Narrative SCS Engineers Lot Number: TB08087

This Report of Analysis contains the analytical result(s) for the sample(s) listed on the Sample Summary following this Case Narrative. The sample receiving date is documented in the header information associated with each sample.

All results listed in this report relate only to the samples that are contained within this report.

Sample receipt, sample analysis, and data review have been performed in accordance with the most current approved NELAC standards, the Shealy Environmental Services, Inc. ("Shealy") Quality Assurance Management Plan (QAMP), standard operating procedures (SOPs), and Shealy policies. Any exceptions to the NELAC standards, the QAMP, SOPs or policies are qualified on the results page or discussed below.

Where applicable, all soil sample analysis are reported on a dry weight basis unless flagged with a "W" qualifier

If you have any questions regarding this report please contact the Shealy Project Manager listed on the cover page.

SHEALY ENVIRONMENTAL SERVICES, INC.

Sample Summary SCS Engineers Lot Number: TB08087

| Sample Number | Sample ID | Matrix | Date Sampled | Date Received |
|---------------|-----------|--------|-----------------|---------------|
| 001 | HJGC | Solid | 02/08/2018 1049 | 02/08/2018 |

(1 sample)

SHEALY ENVIRONMENTAL SERVICES, INC.

Detection Summary

SCS Engineers

Lot Number: TB08087

| Sample | Sample ID | Matrix | Parameter | Method | Result | Q | Units | Page |
|--------|-----------|--------|----------------------|--------|--------|---|-------|------|
| 001 | HJGC | Solid | SGT - HEM (non-polar | 9071B | 1100 | | mg/kg | 5 |
| 001 | HJGC | Solid | Aroclor 1242 | 8082A | 1.3 | | mg/Kg | 8 |
| 001 | HJGC | Solid | Aroclor 1254 | 8082A | 0.34 | | mg/Kg | 8 |
| 001 | HJGC | Solid | Arsenic | 6010D | 0.027 | J | mg/L | 11 |
| 001 | HJGC | Solid | Barium | 6010D | 0.94 | | mg/L | 11 |
| 001 | HJGC | Solid | Chromium | 6010D | 0.036 | J | mg/L | 11 |
| 001 | HJGC | Solid | Lead | 6010D | 0.15 | | mg/L | 11 |

(7 detections)

Inorganic non-metals

| | |
|--------------------------------------|---------------------------------------|
| Client: SCS Engineers | Laboratory ID: TB08087-001 |
| Description: HJGC | Matrix: Solid |
| Date Sampled: 02/08/2018 1049 | % Solids: 65.6 02/14/2018 2116 |
| Date Received: 02/08/2018 | |

| Run | Prep Method | Analytical Method | Dilution | Analysis Date | Analyst | Prep Date | Batch |
|-----|-------------|----------------------|----------|-----------------|---------|-----------|-------|
| 1 | | (SGT - HEM (n) 9071B | 1 | 02/19/2018 0000 | NFB | | 64817 |

| Parameter | CAS Number | Analytical Method | Result | Q | LOQ | DL | Units | Run |
|--------------------------------|------------|-------------------|--------|---|-----|-----|-------|-----|
| SGT - HEM (non-polar material) | | 9071B | 1100 | | 290 | 150 | mg/kg | 1 |

LOQ = Limit of Quantitation B = Detected in the method blank E = Quantitation of compound exceeded the calibration range DL = Detection Limit
 U = Not detected at or above the DL N = Recovery is out of criteria P = The RPD between two GC columns exceeds 40% J = Estimated result < LOQ and ≥ DL
 H = Out of holding time W = Reported on wet weight basis

Shealy Environmental Services, Inc.
 106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Volatiles

| | |
|--------------------------------------|---------------------------------------|
| Client: SCS Engineers | Laboratory ID: TB08087-001 |
| Description: HJGC | Matrix: Solid |
| Date Sampled: 02/08/2018 1049 | % Solids: 65.6 02/14/2018 2116 |
| Date Received: 02/08/2018 | |

| Run | Prep Method | Analytical Method | Dilution | Analysis Date | Analyst | Prep Date | Batch | Leachate Date |
|-----|-------------|-------------------|----------|-----------------|---------|-----------|-------|-----------------|
| 1 | 1311/5030B | 8260B | 10 | 02/13/2018 1406 | JJG | | 64344 | 02/11/2018 1930 |

| Parameter | CAS Number | Analytical Method | Result | Q | LOQ | DL | Units | Run |
|----------------------|------------|-------------------|--------|---|-------|--------|-------|-----|
| Benzene | 71-43-2 | 8260B | 0.0040 | U | 0.050 | 0.0040 | mg/L | 1 |
| 2-Butanone (MEK) | 78-93-3 | 8260B | 0.020 | U | 0.10 | 0.020 | mg/L | 1 |
| Carbon tetrachloride | 56-23-5 | 8260B | 0.0040 | U | 0.050 | 0.0040 | mg/L | 1 |
| Chlorobenzene | 108-90-7 | 8260B | 0.0040 | U | 0.050 | 0.0040 | mg/L | 1 |
| Chloroform | 67-66-3 | 8260B | 0.0040 | U | 0.050 | 0.0040 | mg/L | 1 |
| 1,2-Dichloroethane | 107-06-2 | 8260B | 0.0040 | U | 0.050 | 0.0040 | mg/L | 1 |
| 1,1-Dichloroethene | 75-35-4 | 8260B | 0.0040 | U | 0.050 | 0.0040 | mg/L | 1 |
| Tetrachloroethene | 127-18-4 | 8260B | 0.0040 | U | 0.050 | 0.0040 | mg/L | 1 |
| Trichloroethene | 79-01-6 | 8260B | 0.0040 | U | 0.050 | 0.0040 | mg/L | 1 |
| Vinyl chloride | 75-01-4 | 8260B | 0.0040 | U | 0.010 | 0.0040 | mg/L | 1 |

| Surrogate | Q | Run 1 % Recovery | Acceptance Limits |
|-----------------------|---|------------------|-------------------|
| 1,2-Dichloroethane-d4 | | 100 | 70-130 |
| Bromofluorobenzene | | 101 | 70-130 |
| Toluene-d8 | | 106 | 70-130 |

LOQ = Limit of Quantitation B = Detected in the method blank E = Quantitation of compound exceeded the calibration range DL = Detection Limit
 U = Not detected at or above the DL N = Recovery is out of criteria P = The RPD between two GC columns exceeds 40% J = Estimated result < LOQ and ≥ DL
 H = Out of holding time W = Reported on wet weight basis

Shealy Environmental Services, Inc.
 106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Semivolatiles

| | |
|--------------------------------------|---------------------------------------|
| Client: SCS Engineers | Laboratory ID: TB08087-001 |
| Description: HJGC | Matrix: Solid |
| Date Sampled: 02/08/2018 1049 | % Solids: 65.6 02/14/2018 2116 |
| Date Received: 02/08/2018 | |

| Run | Prep Method | Analytical Method | Dilution | Analysis Date | Analyst | Prep Date | Batch | Leachate Date |
|-----|-------------|-------------------|----------|-----------------|---------|-----------------|-------|-----------------|
| 1 | 1311/3520C | 8270D | 1 | 02/15/2018 1344 | CMP2 | 02/12/2018 1738 | 64269 | 02/11/2018 1930 |

| Parameter | CAS Number | Analytical Method | Result | Q | LOQ | DL | Units | Run |
|-----------------------|------------|-------------------|--------|---|-------|--------|-------|-----|
| 1,4-Dichlorobenzene | 106-46-7 | 8270D | 0.0050 | U | 0.040 | 0.0050 | mg/L | 1 |
| 2,4-Dinitrotoluene | 121-14-2 | 8270D | 0.0050 | U | 0.080 | 0.0050 | mg/L | 1 |
| Hexachlorobenzene | 118-74-1 | 8270D | 0.0050 | U | 0.040 | 0.0050 | mg/L | 1 |
| Hexachlorobutadiene | 87-68-3 | 8270D | 0.0050 | U | 0.040 | 0.0050 | mg/L | 1 |
| Hexachloroethane | 67-72-1 | 8270D | 0.010 | U | 0.040 | 0.010 | mg/L | 1 |
| 2-Methylphenol | 95-48-7 | 8270D | 0.010 | U | 0.040 | 0.010 | mg/L | 1 |
| 3+4-Methylphenol | 106-44-5 | 8270D | 0.015 | U | 0.040 | 0.015 | mg/L | 1 |
| Nitrobenzene | 98-95-3 | 8270D | 0.015 | U | 0.040 | 0.015 | mg/L | 1 |
| Pentachlorophenol | 87-86-5 | 8270D | 0.020 | U | 0.20 | 0.020 | mg/L | 1 |
| Pyridine | 110-86-1 | 8270D | 0.0050 | U | 0.040 | 0.0050 | mg/L | 1 |
| 2,4,5-Trichlorophenol | 95-95-4 | 8270D | 0.0050 | U | 0.040 | 0.0050 | mg/L | 1 |
| 2,4,6-Trichlorophenol | 88-06-2 | 8270D | 0.0050 | U | 0.040 | 0.0050 | mg/L | 1 |

| Surrogate | Q | Run 1 % Recovery | Acceptance Limits |
|----------------------|---|------------------|-------------------|
| 2-Fluorobiphenyl | | 82 | 37-129 |
| 2-Fluorophenol | | 67 | 24-127 |
| Nitrobenzene-d5 | | 106 | 38-127 |
| Phenol-d5 | | 77 | 28-128 |
| Terphenyl-d14 | | 102 | 10-148 |
| 2,4,6-Tribromophenol | | 102 | 41-144 |

LOQ = Limit of Quantitation B = Detected in the method blank E = Quantitation of compound exceeded the calibration range DL = Detection Limit
 U = Not detected at or above the DL N = Recovery is out of criteria P = The RPD between two GC columns exceeds 40% J = Estimated result < LOQ and ≥ DL
 H = Out of holding time W = Reported on wet weight basis

Shealy Environmental Services, Inc.
 106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

PCBs by GC

| | |
|--------------------------------------|---------------------------------------|
| Client: SCS Engineers | Laboratory ID: TB08087-001 |
| Description: HJGC | Matrix: Solid |
| Date Sampled: 02/08/2018 1049 | % Solids: 65.6 02/14/2018 2116 |
| Date Received: 02/08/2018 | |

| Run | Prep Method | Cleanup | Analytical Method | Dilution | Analysis Date | Analyst | Prep Date | Batch |
|-----|-------------|-------------|-------------------|----------|-----------------|---------|-----------------|-------|
| 1 | 3550C | 3660B/3665A | 8082A | 10 | 02/15/2018 1033 | CHG | 02/14/2018 1648 | 64516 |

| Parameter | CAS Number | Analytical Method | Result | Q | LOQ | DL | Units | Run |
|---------------------|-------------------|-------------------|-------------|---|-------------|-------------|--------------|----------|
| Aroclor 1016 | 12674-11-2 | 8082A | 0.06 | U | 0.26 | 0.06 | mg/Kg | 1 |
| Aroclor 1221 | 11104-28-2 | 8082A | 0.06 | U | 0.26 | 0.06 | mg/Kg | 1 |
| Aroclor 1232 | 11141-16-5 | 8082A | 0.06 | U | 0.26 | 0.06 | mg/Kg | 1 |
| Aroclor 1242 | 53469-21-9 | 8082A | 1.3 | | 0.26 | 0.06 | mg/Kg | 1 |
| Aroclor 1248 | 12672-29-6 | 8082A | 0.06 | U | 0.26 | 0.06 | mg/Kg | 1 |
| Aroclor 1254 | 11097-69-1 | 8082A | 0.34 | | 0.26 | 0.06 | mg/Kg | 1 |
| Aroclor 1260 | 11096-82-5 | 8082A | 0.06 | U | 0.26 | 0.06 | mg/Kg | 1 |

| Surrogate | Q | Run 1 % Recovery | Acceptance Limits |
|----------------------|---|------------------|-------------------|
| Decachlorobiphenyl | | 102 | 41-132 |
| Tetrachloro-m-xylene | | 78 | 35-106 |

LOQ = Limit of Quantitation B = Detected in the method blank E = Quantitation of compound exceeded the calibration range DL = Detection Limit
 U = Not detected at or above the DL N = Recovery is out of criteria P = The RPD between two GC columns exceeds 40% J = Estimated result < LOQ and ≥ DL
 H = Out of holding time W = Reported on wet weight basis

Shealy Environmental Services, Inc.
 106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Herbicides

| | |
|--------------------------------------|---------------------------------------|
| Client: SCS Engineers | Laboratory ID: TB08087-001 |
| Description: HJGC | Matrix: Solid |
| Date Sampled: 02/08/2018 1049 | % Solids: 65.6 02/14/2018 2116 |
| Date Received: 02/08/2018 | |

| Run | Prep Method | Analytical Method | Dilution | Analysis Date | Analyst | Prep Date | Batch | Leachate Date |
|-----|-------------|-------------------|----------|-----------------|---------|-----------------|-------|-----------------|
| 1 | 1311/8151A | 8151A | 1 | 02/15/2018 1447 | DAL1 | 02/13/2018 1941 | 64366 | 02/11/2018 1930 |

| Parameter | CAS Number | Analytical Method | Result | Q | LOQ | DL | Units | Run |
|-------------------|------------|-------------------|--------|---|--------|--------|-------|-----|
| 2,4-D | 94-75-7 | 8151A | 0.0050 | U | 0.020 | 0.0050 | mg/L | 1 |
| 2,4,5-TP (Silvex) | 93-72-1 | 8151A | 0.0013 | U | 0.0050 | 0.0013 | mg/L | 1 |

| Surrogate | Q | Run 1 % Recovery | Acceptance Limits |
|-----------|---|------------------|-------------------|
| DCAA | | 83 | 62-117 |

LOQ = Limit of Quantitation B = Detected in the method blank E = Quantitation of compound exceeded the calibration range DL = Detection Limit
 U = Not detected at or above the DL N = Recovery is out of criteria P = The RPD between two GC columns exceeds 40% J = Estimated result < LOQ and ≥ DL
 H = Out of holding time W = Reported on wet weight basis

Shealy Environmental Services, Inc.
 106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Pesticides

| | |
|--------------------------------------|---------------------------------------|
| Client: SCS Engineers | Laboratory ID: TB08087-001 |
| Description: HJGC | Matrix: Solid |
| Date Sampled: 02/08/2018 1049 | % Solids: 65.6 02/14/2018 2116 |
| Date Received: 02/08/2018 | |

| Run | Prep Method | Analytical Method | Dilution | Analysis Date | Analyst | Prep Date | Batch | Leachate Date |
|-----|-------------|-------------------|----------|-----------------|---------|-----------------|-------|-----------------|
| 1 | 1311/3520C | 8081B | 1 | 02/13/2018 1730 | PMS | 02/12/2018 1738 | 64285 | 02/11/2018 1930 |

| Parameter | CAS Number | Analytical Method | Result | Q | LOQ | DL | Units | Run |
|---------------------|------------|-------------------|---------|---|---------|---------|-------|-----|
| gamma-BHC (Lindane) | 58-89-9 | 8081B | 0.00017 | U | 0.00040 | 0.00017 | mg/L | 1 |
| Chlordane | 57-74-9 | 8081B | 0.0015 | U | 0.0040 | 0.0015 | mg/L | 1 |
| Endrin | 72-20-8 | 8081B | 0.00015 | U | 0.00040 | 0.00015 | mg/L | 1 |
| Heptachlor | 76-44-8 | 8081B | 0.00015 | U | 0.00040 | 0.00015 | mg/L | 1 |
| Heptachlor epoxide | 1024-57-3 | 8081B | 0.00016 | U | 0.00040 | 0.00016 | mg/L | 1 |
| Methoxychlor | 72-43-5 | 8081B | 0.00021 | U | 0.0016 | 0.00021 | mg/L | 1 |
| Toxaphene | 8001-35-2 | 8081B | 0.0030 | U | 0.0080 | 0.0030 | mg/L | 1 |

| Surrogate | Q | Run 1 % Recovery | Acceptance Limits |
|----------------------|---|------------------|-------------------|
| Decachlorobiphenyl | | 89 | 20-131 |
| Tetrachloro-m-xylene | | 76 | 26-132 |

LOQ = Limit of Quantitation B = Detected in the method blank E = Quantitation of compound exceeded the calibration range DL = Detection Limit
 U = Not detected at or above the DL N = Recovery is out of criteria P = The RPD between two GC columns exceeds 40% J = Estimated result < LOQ and ≥ DL
 H = Out of holding time W = Reported on wet weight basis

Shealy Environmental Services, Inc.
 106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Metals

| | |
|--------------------------------------|---------------------------------------|
| Client: SCS Engineers | Laboratory ID: TB08087-001 |
| Description: HJGC | Matrix: Solid |
| Date Sampled: 02/08/2018 1049 | % Solids: 65.6 02/14/2018 2116 |
| Date Received: 02/08/2018 | |

| Run | Prep Method | Analytical Method | Dilution | Analysis Date | Analyst | Prep Date | Batch | Leachate Date |
|-----|-------------|-------------------|----------|-----------------|---------|-----------------|-------|-----------------|
| 1 | 1311/3010A | 6010D | 1 | 02/15/2018 1310 | CJZ | 02/13/2018 1737 | 64381 | 02/11/2018 1930 |
| 1 | 1311/7470A | 7470A | 1 | 02/13/2018 2034 | SLS | 02/13/2018 1512 | 64353 | 02/11/2018 1930 |

| Parameter | CAS Number | Analytical Method | Result | Q | LOQ | DL | Units | Run |
|-----------------|------------------|-------------------|--------------|----------|-------------|--------------|-------------|----------|
| Arsenic | 7440-38-2 | 6010D | 0.027 | J | 0.15 | 0.025 | mg/L | 1 |
| Barium | 7440-39-3 | 6010D | 0.94 | | 0.25 | 0.031 | mg/L | 1 |
| Cadmium | 7440-43-9 | 6010D | 0.0060 | U | 0.050 | 0.0060 | mg/L | 1 |
| Chromium | 7440-47-3 | 6010D | 0.036 | J | 0.10 | 0.013 | mg/L | 1 |
| Lead | 7439-92-1 | 6010D | 0.15 | | 0.10 | 0.047 | mg/L | 1 |
| Mercury | 7439-97-6 | 7470A | 0.00091 | U | 0.0020 | 0.00091 | mg/L | 1 |
| Selenium | 7782-49-2 | 6010D | 0.085 | U | 0.20 | 0.085 | mg/L | 1 |
| Silver | 7440-22-4 | 6010D | 0.021 | U | 0.10 | 0.021 | mg/L | 1 |

LOQ = Limit of Quantitation B = Detected in the method blank E = Quantitation of compound exceeded the calibration range DL = Detection Limit
 U = Not detected at or above the DL N = Recovery is out of criteria P = The RPD between two GC columns exceeds 40% J = Estimated result < LOQ and ≥ DL
 H = Out of holding time W = Reported on wet weight basis

Shealy Environmental Services, Inc.
 106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

QC Summary

Inorganic non-metals - MB

Sample ID: TQ64817-001

Matrix: Solid

Batch: 64817

Analytical Method: 9071B

| Parameter | Result | Q | Dil | LOQ | DL | Units | Analysis Date |
|--------------------------------|--------|---|-----|-----|-----|-------|-----------------|
| SGT - HEM (non-polar material) | 100 | U | 1 | 200 | 100 | mg/kg | 02/19/2018 0000 |

LOQ = Limit of Quantitation

DL = Detection Limit

LOD = Limit of Detection

P = The RPD between two GC columns exceeds 40%

J = Estimated result < LOQ and \geq DL

U = Not detected at or above the detection limit

N = Recovery is out of criteria

+ = RPD is out of criteria

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

Inorganic non-metals - LCS

Sample ID: TQ64817-002

Matrix: Solid

Batch: 64817

Analytical Method: 9071B

| Parameter | Spike Amount (mg/kg) | Result (mg/kg) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|--------------------------------|----------------------|----------------|---|-----|-------|-------------|-----------------|
| SGT - HEM (non-polar material) | 1000 | 820 | | 1 | 82 | 70-130 | 02/19/2018 0000 |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and \geq DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

Inorganic non-metals - Duplicate

Sample ID: TB08087-001DU

Matrix: Solid

Batch: 64817

Analytical Method: 9071B

| Parameter | Sample Amount (mg/kg) | Result (mg/kg) | Q | Dil | % RPD | % RPD Limit | Analysis Date |
|--------------------------------|-----------------------|----------------|---|-----|-------|-------------|-----------------|
| SGT - HEM (non-polar material) | 1100 | 1100 | + | 1 | 39 | 20 | 02/19/2018 0000 |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and \geq DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

Inorganic non-metals - MS

Sample ID: TB08087-001MS

Matrix: Solid

Batch: 64817

Analytical Method: 9071B

| Parameter | Sample Amount (mg/kg) | Spike Amount (mg/kg) | Result (mg/kg) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|--------------------------------|-----------------------|----------------------|----------------|---|-----|-------|-------------|-----------------|
| SGT - HEM (non-polar material) | 1100 | 1500 | 3000 | N | 1 | 153 | 70-130 | 02/19/2018 0000 |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and \geq DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Volatiles - MB

Sample ID: TQ64344-001

Matrix: Solid

Batch: 64344

Prep Method: 1311/5030B

Analytical Method: 8260B

Leachate Date: 02/11/2018 1930

| Parameter | Result | Q | Dil | LOQ | DL | Units | Analysis Date |
|-----------------------|--------|-------|------------------|-------|--------|-------|-----------------|
| Benzene | 0.0040 | U | 10 | 0.050 | 0.0040 | mg/L | 02/13/2018 1256 |
| 2-Butanone (MEK) | 0.020 | U | 10 | 0.10 | 0.020 | mg/L | 02/13/2018 1256 |
| Carbon tetrachloride | 0.0040 | U | 10 | 0.050 | 0.0040 | mg/L | 02/13/2018 1256 |
| Chlorobenzene | 0.0040 | U | 10 | 0.050 | 0.0040 | mg/L | 02/13/2018 1256 |
| Chloroform | 0.0040 | U | 10 | 0.050 | 0.0040 | mg/L | 02/13/2018 1256 |
| 1,2-Dichloroethane | 0.0040 | U | 10 | 0.050 | 0.0040 | mg/L | 02/13/2018 1256 |
| 1,1-Dichloroethene | 0.0040 | U | 10 | 0.050 | 0.0040 | mg/L | 02/13/2018 1256 |
| Tetrachloroethene | 0.0040 | U | 10 | 0.050 | 0.0040 | mg/L | 02/13/2018 1256 |
| Trichloroethene | 0.0040 | U | 10 | 0.050 | 0.0040 | mg/L | 02/13/2018 1256 |
| Vinyl chloride | 0.0040 | U | 10 | 0.010 | 0.0040 | mg/L | 02/13/2018 1256 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | |
| 1,2-Dichloroethane-d4 | | 111 | 70-130 | | | | |
| Bromofluorobenzene | | 108 | 70-130 | | | | |
| Toluene-d8 | | 111 | 70-130 | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Volatiles - LCS

Sample ID: TQ64344-002

Matrix: Solid

Batch: 64344

Prep Method: 1311/5030B

Analytical Method: 8260B

Leachate Date: 02/11/2018 1930

| Parameter | Spike Amount (mg/L) | Result (mg/L) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|-----------------------|---------------------|---------------|------------------|-----|-------|-------------|-----------------|
| Benzene | 0.50 | 0.54 | | 10 | 108 | 70-130 | 02/13/2018 1233 |
| 2-Butanone (MEK) | 1.0 | 1.0 | | 10 | 105 | 70-130 | 02/13/2018 1233 |
| Carbon tetrachloride | 0.50 | 0.58 | | 10 | 117 | 70-130 | 02/13/2018 1233 |
| Chlorobenzene | 0.50 | 0.53 | | 10 | 106 | 70-130 | 02/13/2018 1233 |
| Chloroform | 0.50 | 0.57 | | 10 | 113 | 70-130 | 02/13/2018 1233 |
| 1,2-Dichloroethane | 0.50 | 0.57 | | 10 | 114 | 70-130 | 02/13/2018 1233 |
| 1,1-Dichloroethene | 0.50 | 0.56 | | 10 | 112 | 70-130 | 02/13/2018 1233 |
| Tetrachloroethene | 0.50 | 0.53 | | 10 | 107 | 70-130 | 02/13/2018 1233 |
| Trichloroethene | 0.50 | 0.54 | | 10 | 109 | 70-130 | 02/13/2018 1233 |
| Vinyl chloride | 0.50 | 0.56 | | 10 | 113 | 70-130 | 02/13/2018 1233 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | |
| 1,2-Dichloroethane-d4 | | 96 | 70-130 | | | | |
| Bromofluorobenzene | | 99 | 70-130 | | | | |
| Toluene-d8 | | 101 | 70-130 | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and \geq DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Volatiles - MS

Sample ID: TB08087-001MS

Matrix: Solid

Batch: 64344

Prep Method: 1311/5030B

Analytical Method: 8260B

Leachate Date: 02/11/2018 1930

| Parameter | Sample Amount (mg/L) | Spike Amount (mg/L) | Result (mg/L) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|-----------------------|----------------------|---------------------|------------------|---|-----|-------|-------------|-----------------|
| Benzene | 0.0 | 0.50 | 0.59 | | 10 | 117 | 70-130 | 02/13/2018 1429 |
| 2-Butanone (MEK) | 0.0 | 1.0 | 1.0 | | 10 | 103 | 70-130 | 02/13/2018 1429 |
| Carbon tetrachloride | 0.0 | 0.50 | 0.64 | | 10 | 127 | 70-130 | 02/13/2018 1429 |
| Chlorobenzene | 0.0 | 0.50 | 0.56 | | 10 | 113 | 70-130 | 02/13/2018 1429 |
| Chloroform | 0.0 | 0.50 | 0.60 | | 10 | 121 | 70-130 | 02/13/2018 1429 |
| 1,2-Dichloroethane | 0.0 | 0.50 | 0.58 | | 10 | 117 | 70-130 | 02/13/2018 1429 |
| 1,1-Dichloroethene | 0.0 | 0.50 | 0.61 | | 10 | 123 | 70-130 | 02/13/2018 1429 |
| Tetrachloroethene | 0.0 | 0.50 | 0.58 | | 10 | 115 | 70-130 | 02/13/2018 1429 |
| Trichloroethene | 0.0 | 0.50 | 0.59 | | 10 | 118 | 70-130 | 02/13/2018 1429 |
| Vinyl chloride | 0.0 | 0.50 | 0.63 | | 10 | 126 | 70-130 | 02/13/2018 1429 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | | |
| 1,2-Dichloroethane-d4 | | 99 | 70-130 | | | | | |
| Bromofluorobenzene | | 103 | 70-130 | | | | | |
| Toluene-d8 | | 106 | 70-130 | | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Semivolatiles - MB

Sample ID: TQ64269-001

Matrix: Solid

Batch: 64269

Prep Method: 1311/3520C

Analytical Method: 8270D

Prep Date: 02/12/2018 1738 Leachate Date: 02/11/2018 1930

| Parameter | Result | Q | Dil | LOQ | DL | Units | Analysis Date |
|-----------------------|--------|---|-----|-------|--------|-------|-----------------|
| 1,4-Dichlorobenzene | 0.0050 | U | 1 | 0.040 | 0.0050 | mg/L | 02/15/2018 1029 |
| 2,4-Dinitrotoluene | 0.0050 | U | 1 | 0.080 | 0.0050 | mg/L | 02/15/2018 1029 |
| Hexachlorobenzene | 0.0050 | U | 1 | 0.040 | 0.0050 | mg/L | 02/15/2018 1029 |
| Hexachlorobutadiene | 0.0050 | U | 1 | 0.040 | 0.0050 | mg/L | 02/15/2018 1029 |
| Hexachloroethane | 0.010 | U | 1 | 0.040 | 0.010 | mg/L | 02/15/2018 1029 |
| 2-Methylphenol | 0.010 | U | 1 | 0.040 | 0.010 | mg/L | 02/15/2018 1029 |
| 3+4-Methylphenol | 0.015 | U | 1 | 0.040 | 0.015 | mg/L | 02/15/2018 1029 |
| Nitrobenzene | 0.015 | U | 1 | 0.040 | 0.015 | mg/L | 02/15/2018 1029 |
| Pentachlorophenol | 0.020 | U | 1 | 0.20 | 0.020 | mg/L | 02/15/2018 1029 |
| Pyridine | 0.0050 | U | 1 | 0.040 | 0.0050 | mg/L | 02/15/2018 1029 |
| 2,4,5-Trichlorophenol | 0.0050 | U | 1 | 0.040 | 0.0050 | mg/L | 02/15/2018 1029 |
| 2,4,6-Trichlorophenol | 0.0050 | U | 1 | 0.040 | 0.0050 | mg/L | 02/15/2018 1029 |

| Surrogate | Q | % Rec | Acceptance Limit |
|----------------------|---|-------|------------------|
| 2-Fluorobiphenyl | | 83 | 37-129 |
| 2-Fluorophenol | | 54 | 24-127 |
| Nitrobenzene-d5 | | 93 | 38-127 |
| Phenol-d5 | | 64 | 28-128 |
| Terphenyl-d14 | | 100 | 10-148 |
| 2,4,6-Tribromophenol | | 102 | 41-144 |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Semivolatiles - LCS

Sample ID: TQ64269-002

Matrix: Solid

Batch: 64269

Prep Method: 1311/3520C

Analytical Method: 8270D

Prep Date: 02/12/2018 1738 Leachate Date: 02/11/2018 1930

| Parameter | Spike Amount (mg/L) | Result (mg/L) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|-----------------------|---------------------|---------------|------------------|-----|-------|-------------|-----------------|
| 1,4-Dichlorobenzene | 0.40 | 0.27 | | 1 | 68 | 30-130 | 02/15/2018 1053 |
| 2,4-Dinitrotoluene | 0.40 | 0.36 | | 1 | 90 | 30-130 | 02/15/2018 1053 |
| Hexachlorobenzene | 0.40 | 0.42 | | 1 | 105 | 30-130 | 02/15/2018 1053 |
| Hexachlorobutadiene | 0.40 | 0.21 | | 1 | 53 | 30-130 | 02/15/2018 1053 |
| Hexachloroethane | 0.40 | 0.22 | | 1 | 56 | 30-130 | 02/15/2018 1053 |
| 2-Methylphenol | 0.40 | 0.36 | | 1 | 90 | 30-130 | 02/15/2018 1053 |
| 3+4-Methylphenol | 0.80 | 0.85 | | 1 | 106 | 30-130 | 02/15/2018 1053 |
| Nitrobenzene | 0.40 | 0.44 | | 1 | 111 | 30-130 | 02/15/2018 1053 |
| Pentachlorophenol | 0.40 | 0.36 | | 1 | 90 | 30-130 | 02/15/2018 1053 |
| Pyridine | 0.40 | 0.39 | | 1 | 97 | 30-130 | 02/15/2018 1053 |
| 2,4,5-Trichlorophenol | 0.40 | 0.38 | | 1 | 95 | 30-130 | 02/15/2018 1053 |
| 2,4,6-Trichlorophenol | 0.40 | 0.34 | | 1 | 86 | 30-130 | 02/15/2018 1053 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | |
| 2-Fluorobiphenyl | | 85 | 37-129 | | | | |
| 2-Fluorophenol | | 68 | 24-127 | | | | |
| Nitrobenzene-d5 | | 108 | 38-127 | | | | |
| Phenol-d5 | | 83 | 28-128 | | | | |
| Terphenyl-d14 | | 99 | 10-148 | | | | |
| 2,4,6-Tribromophenol | | 100 | 41-144 | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Pesticides - MB

Sample ID: TQ64285-001

Matrix: Solid

Batch: 64285

Prep Method: 1311/3520C

Analytical Method: 8081B

Prep Date: 02/12/2018 1738 Leachate Date: 02/11/2018 1930

| Parameter | Result | Q | Dil | LOQ | DL | Units | Analysis Date |
|----------------------|---------|-------|------------------|---------|---------|-------|-----------------|
| gamma-BHC (Lindane) | 0.00017 | U | 1 | 0.00040 | 0.00017 | mg/L | 02/13/2018 1644 |
| Chlordane | 0.0015 | U | 1 | 0.0040 | 0.0015 | mg/L | 02/13/2018 1644 |
| Endrin | 0.00015 | U | 1 | 0.00040 | 0.00015 | mg/L | 02/13/2018 1644 |
| Heptachlor | 0.00015 | U | 1 | 0.00040 | 0.00015 | mg/L | 02/13/2018 1644 |
| Heptachlor epoxide | 0.00016 | U | 1 | 0.00040 | 0.00016 | mg/L | 02/13/2018 1644 |
| Methoxychlor | 0.00021 | U | 1 | 0.0016 | 0.00021 | mg/L | 02/13/2018 1644 |
| Toxaphene | 0.0030 | U | 1 | 0.0080 | 0.0030 | mg/L | 02/13/2018 1644 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | |
| Decachlorobiphenyl | | 93 | 20-131 | | | | |
| Tetrachloro-m-xylene | | 82 | 26-132 | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and \geq DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Pesticides - LCS

Sample ID: TQ64285-002

Matrix: Solid

Batch: 64285

Prep Method: 1311/3520C

Analytical Method: 8081B

Prep Date: 02/12/2018 1738 Leachate Date: 02/11/2018 1930

| Parameter | Spike Amount (mg/L) | Result (mg/L) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|----------------------|---------------------|---------------|------------------|-----|-------|-------------|-----------------|
| gamma-BHC (Lindane) | 0.0080 | 0.0078 | | 1 | 98 | 70-130 | 02/13/2018 1659 |
| Chlordane | 0.0080 | 0.0098 | P | 1 | 123 | 70-130 | 02/13/2018 1659 |
| Endrin | 0.0080 | 0.0074 | | 1 | 93 | 70-130 | 02/13/2018 1659 |
| Heptachlor | 0.0080 | 0.0075 | | 1 | 94 | 70-130 | 02/13/2018 1659 |
| Heptachlor epoxide | 0.0080 | 0.0072 | | 1 | 90 | 70-130 | 02/13/2018 1659 |
| Methoxychlor | 0.0080 | 0.0079 | | 1 | 99 | 70-130 | 02/13/2018 1659 |
| Toxaphene | 0.016 | 0.015 | | 1 | 94 | 70-130 | 02/13/2018 1659 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | |
| Decachlorobiphenyl | | 101 | 20-131 | | | | |
| Tetrachloro-m-xylene | | 84 | 26-132 | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Pesticides - MS

Sample ID: TB08087-001MS

Matrix: Solid

Batch: 64285

Prep Method: 1311/3520C

Analytical Method: 8081B

Prep Date: 02/12/2018 1738 Leachate Date: 02/11/2018 1930

| Parameter | Sample Amount (mg/L) | Spike Amount (mg/L) | Result (mg/L) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|----------------------|----------------------|---------------------|------------------|---|-----|-------|-------------|-----------------|
| gamma-BHC (Lindane) | 0.0 | 0.0080 | 0.0078 | | 1 | 98 | 70-130 | 02/13/2018 1746 |
| Chlordane | 0.0 | 0.0080 | 0.0057 | P | 1 | 71 | 70-130 | 02/13/2018 1746 |
| Endrin | 0.0 | 0.0080 | 0.0072 | | 1 | 90 | 70-130 | 02/13/2018 1746 |
| Heptachlor | 0.0 | 0.0080 | 0.0072 | | 1 | 90 | 70-130 | 02/13/2018 1746 |
| Heptachlor epoxide | 0.0 | 0.0080 | 0.0068 | | 1 | 85 | 70-130 | 02/13/2018 1746 |
| Methoxychlor | 0.0 | 0.0080 | 0.0080 | | 1 | 100 | 70-130 | 02/13/2018 1746 |
| Toxaphene | 0.0 | 0.016 | 0.013 | | 1 | 83 | 70-130 | 02/13/2018 1746 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | | |
| Decachlorobiphenyl | | 96 | 20-131 | | | | | |
| Tetrachloro-m-xylene | | 76 | 26-132 | | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Herbicides - MB

Sample ID: TQ64366-001

Matrix: Solid

Batch: 64366

Prep Method: 1311/8151A

Analytical Method: 8151A

Prep Date: 02/13/2018 1941 Leachate Date: 02/11/2018 1930

| Parameter | Result | Q | Dil | LOQ | DL | Units | Analysis Date |
|-------------------|--------|-------|---------------------|--------|--------|-------|-----------------|
| 2,4-D | 0.0050 | U | 1 | 0.020 | 0.0050 | mg/L | 02/14/2018 1526 |
| 2,4,5-TP (Silvex) | 0.0013 | U | 1 | 0.0050 | 0.0013 | mg/L | 02/14/2018 1526 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | |
| DCAA | | 80 | 62-117 | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Herbicides - LCS

Sample ID: TQ64366-002

Matrix: Solid

Batch: 64366

Prep Method: 1311/8151A

Analytical Method: 8151A

Prep Date: 02/13/2018 1941 Leachate Date: 02/11/2018 1930

| Parameter | Spike Amount (mg/L) | Result (mg/L) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|-------------------|---------------------|---------------|------------------|-----|-------|-------------|-----------------|
| 2,4-D | 0.20 | 0.14 | | 1 | 72 | 59-139 | 02/14/2018 1549 |
| 2,4,5-TP (Silvex) | 0.20 | 0.17 | | 1 | 84 | 56-132 | 02/14/2018 1549 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | |
| DCAA | | 89 | 62-117 | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and \geq DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Herbicides - MS

Sample ID: TB08087-001MS

Matrix: Solid

Batch: 64366

Prep Method: 1311/8151A

Analytical Method: 8151A

Prep Date: 02/13/2018 1941 Leachate Date: 02/11/2018 1930

| Parameter | Sample Amount (mg/L) | Spike Amount (mg/L) | Result (mg/L) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|-------------------|----------------------|---------------------|------------------|---|-----|-------|-------------|-----------------|
| 2,4-D | 0.0 | 0.20 | 0.13 | | 1 | 63 | 59-139 | 02/15/2018 1510 |
| 2,4,5-TP (Silvex) | 0.0 | 0.20 | 0.15 | | 1 | 74 | 56-132 | 02/15/2018 1510 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | | |
| DCAA | | 86 | 62-117 | | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

PCBs by GC - MB

Sample ID: TQ64516-001

Matrix: Solid

Batch: 64516

Prep Method: 3550C

Cleanup: 3660B/3665A

Analytical Method: 8082A

Prep Date: 02/14/2018 1648

| Parameter | Result | Q | Dil | LOQ | DL | Units | Analysis Date |
|--------------|--------|---|-----|-------|-------|-------|-----------------|
| Aroclor 1016 | 0.004 | U | 1 | 0.017 | 0.004 | mg/Kg | 02/15/2018 0953 |
| Aroclor 1221 | 0.004 | U | 1 | 0.017 | 0.004 | mg/Kg | 02/15/2018 0953 |
| Aroclor 1232 | 0.004 | U | 1 | 0.017 | 0.004 | mg/Kg | 02/15/2018 0953 |
| Aroclor 1242 | 0.004 | U | 1 | 0.017 | 0.004 | mg/Kg | 02/15/2018 0953 |
| Aroclor 1248 | 0.004 | U | 1 | 0.017 | 0.004 | mg/Kg | 02/15/2018 0953 |
| Aroclor 1254 | 0.004 | U | 1 | 0.017 | 0.004 | mg/Kg | 02/15/2018 0953 |
| Aroclor 1260 | 0.004 | U | 1 | 0.017 | 0.004 | mg/Kg | 02/15/2018 0953 |

| Surrogate | Q | % Rec | Acceptance Limit |
|----------------------|---|-------|------------------|
| Decachlorobiphenyl | | 54 | 41-132 |
| Tetrachloro-m-xylene | | 51 | 35-106 |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

PCBs by GC - LCS

Sample ID: TQ64516-002

Matrix: Solid

Batch: 64516

Prep Method: 3550C

Cleanup: 3660B/3665A

Analytical Method: 8082A

Prep Date: 02/14/2018 1648

| Parameter | Spike Amount (mg/Kg) | Result (mg/Kg) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|----------------------|----------------------|----------------|------------------|-----|-------|-------------|-----------------|
| Aroclor 1016 | 0.083 | 0.071 | | 1 | 86 | 70-130 | 02/15/2018 1006 |
| Aroclor 1260 | 0.083 | 0.067 | | 1 | 81 | 70-130 | 02/15/2018 1006 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | |
| Decachlorobiphenyl | | 93 | 41-132 | | | | |
| Tetrachloro-m-xylene | | 80 | 35-106 | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and \geq DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

PCBs by GC - MS

Sample ID: TB08087-001MS

Matrix: Solid

Batch: 64516

Prep Method: 3550C

Cleanup: 3660B/3665A

Analytical Method: 8082A

Prep Date: 02/14/2018 1648

| Parameter | Sample Amount (mg/Kg) | Spike Amount (mg/Kg) | Result (mg/Kg) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|----------------------|-----------------------|----------------------|------------------|---|-----|-------|-------------|-----------------|
| Aroclor 1016 | 0 | 0.12 | 0.31 | N | 10 | 252 | 70-130 | 02/15/2018 1046 |
| Aroclor 1260 | 0 | 0.12 | 0.12 | | 10 | 98 | 70-130 | 02/15/2018 1046 |
| Surrogate | Q | % Rec | Acceptance Limit | | | | | |
| Decachlorobiphenyl | | 55 | 41-132 | | | | | |
| Tetrachloro-m-xylene | | 41 | 35-106 | | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

PCBs by GC - MSD

Sample ID: TB08087-001MD

Matrix: Solid

Batch: 64516

Prep Method: 3550C

Cleanup: 3660B/3665A

Analytical Method: 8082A

Prep Date: 02/14/2018 1648

| Parameter | Sample Amount (mg/Kg) | Spike Amount (mg/Kg) | Result (mg/Kg) | Q | Dil | % Rec | % RPD | % Rec Limit | % RPD Limit | Analysis Date | |
|----------------------|-----------------------|----------------------|------------------|-----|-----|-------|-------|-------------|-------------|-----------------|--|
| Aroclor 1016 | 0 | 0.13 | 0.43 | N,+ | 10 | 340 | 31 | 70-130 | 20 | 02/15/2018 1059 | |
| Aroclor 1260 | 0 | 0.13 | 0.13 | P | 10 | 105 | 7.9 | 70-130 | 20 | 02/15/2018 1059 | |
| Surrogate | Q | % Rec | Acceptance Limit | | | | | | | | |
| Decachlorobiphenyl | | 94 | 41-132 | | | | | | | | |
| Tetrachloro-m-xylene | | 79 | 35-106 | | | | | | | | |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Metals - MB

Sample ID: TQ64381-001

Matrix: Solid

Batch: 64381

Prep Method: 1311/3010A

Analytical Method: 6010D

Prep Date: 02/13/2018 1737 Leachate Date: 02/11/2018 1930

| Parameter | Result | Q | Dil | LOQ | DL | Units | Analysis Date |
|----------------|---------------|----------|----------|---------------|----------------|-------------|------------------------|
| Arsenic | 0.0025 | U | 1 | 0.015 | 0.0025 | mg/L | 02/15/2018 1231 |
| Barium | 0.0044 | J | 1 | 0.025 | 0.0031 | mg/L | 02/15/2018 1231 |
| Cadmium | 0.0060 | | 1 | 0.0050 | 0.00060 | mg/L | 02/15/2018 1231 |
| Chromium | 0.0013 | U | 1 | 0.010 | 0.0013 | mg/L | 02/15/2018 1231 |
| Lead | 0.013 | | 1 | 0.010 | 0.0047 | mg/L | 02/15/2018 1231 |
| Selenium | 0.0085 | U | 1 | 0.020 | 0.0085 | mg/L | 02/15/2018 1231 |
| Silver | 0.0021 | U | 1 | 0.010 | 0.0021 | mg/L | 02/15/2018 1231 |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and ≥ DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Metals - LCS

Sample ID: TQ64381-002

Matrix: Solid

Batch: 64381

Prep Method: 1311/3010A

Analytical Method: 6010D

Prep Date: 02/13/2018 1737 Leachate Date: 02/11/2018 1930

| Parameter | Spike Amount (mg/L) | Result (mg/L) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|-----------|---------------------|---------------|---|-----|-------|-------------|-----------------|
| Arsenic | 50 | 47 | | 1 | 93 | 80-120 | 02/15/2018 1236 |
| Barium | 100 | 94 | | 1 | 94 | 80-120 | 02/15/2018 1236 |
| Cadmium | 10 | 9.3 | | 1 | 93 | 80-120 | 02/15/2018 1236 |
| Chromium | 50 | 50 | | 1 | 101 | 80-120 | 02/15/2018 1236 |
| Lead | 50 | 48 | | 1 | 97 | 80-120 | 02/15/2018 1236 |
| Selenium | 10 | 9.4 | | 1 | 94 | 80-120 | 02/15/2018 1236 |
| Silver | 10 | 10 | | 1 | 100 | 80-120 | 02/15/2018 1236 |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and \geq DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Metals - MB

Sample ID: TQ64353-001

Matrix: Solid

Batch: 64353

Prep Method: 1311/7470A

Analytical Method: 7470A

Prep Date: 02/13/2018 1512 Leachate Date: 02/11/2018 1930

| Parameter | Result | Q | Dil | LOQ | DL | Units | Analysis Date |
|-----------|----------|---|-----|---------|----------|-------|-----------------|
| Mercury | 0.000091 | U | 1 | 0.00020 | 0.000091 | mg/L | 02/13/2018 2020 |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and \geq DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

TCLP Metals - LCS

Sample ID: TQ64353-002

Matrix: Solid

Batch: 64353

Prep Method: 1311/7470A

Analytical Method: 7470A

Prep Date: 02/13/2018 1512 Leachate Date: 02/11/2018 1930

| Parameter | Spike Amount (mg/L) | Result (mg/L) | Q | Dil | % Rec | % Rec Limit | Analysis Date |
|-----------|---------------------|---------------|---|-----|-------|-------------|-----------------|
| Mercury | 0.020 | 0.021 | | 1 | 107 | 80-120 | 02/13/2018 2023 |

LOQ = Limit of Quantitation

P = The RPD between two GC columns exceeds 40%

N = Recovery is out of criteria

DL = Detection Limit

J = Estimated result < LOQ and \geq DL

+ = RPD is out of criteria

LOD = Limit of Detection

U = Not detected at or above the detection limit

Note: Calculations are performed before rounding to avoid round-off errors in calculated results

Shealy Environmental Services, Inc.

106 Vantage Point Drive West Columbia, SC 29172 (803) 791-9700 Fax (803) 791-9111 www.shealylab.com

**Chain of Custody
and
Miscellaneous Documents**

SHEALY ENVIRONMENTAL SERVICES, INC.



Chain of Custody Record

SHEALY ENVIRONMENTAL SERVICES, INC.
 106 Vantage Point Drive • West Columbia, SC 29172
 Telephone No. 803-791-9700 Fax No. 803-791-9111
 www.shealylab.com

Number **79662**

| | | | |
|--|---|--|--|
| Client SCS Engineers Address 2520 Whitehall Park Dr #450 City Charlotte State NC Zip Code 28273 Project Name RAYCLIFF E. Golf. Fen. Pres GC DESIGN Project No. 08217302.00 Sample ID / Description (Containers for each sample may be combined on one line.) HIGC | Report to Contact STEVE LAMB Sampler's Signature Printed Name Steve Lamb Telephone No. / E-mail 811 WINDSOR SCSEENGINEERS.COM Analysis (Attach list if more space is needed) TRLP VEC TRLP SVEC TRLP Metals TRLP Pest TRLP Herb Total PCBs TRLP-HHSGT 90710 | Matrix No of Containers by Matrix Type Matrix Date Time 08/08/18 10:49 AM | Quota No. 20795 Page 1 of 1 TB08087 MMS Remarks / Cooler I.D. |
| Turn Around Time Required (Prior lab approval required for expedited TAT.) <input type="checkbox"/> Standard <input type="checkbox"/> Rush (Specify) | | Possible Hazard Identification <input type="checkbox"/> Non-Hazard <input type="checkbox"/> Flammable <input type="checkbox"/> Skin Irritant <input type="checkbox"/> Poison <input type="checkbox"/> Unknown | |
| 1. Relinquished by JALLEN THOMAS | | 1. Relinquished by | |
| 2. Relinquished by | | 2. Relinquished by | |
| 3. Relinquished by | | 3. Relinquished by | |
| 4. Relinquished by | | 4. Relinquished by | |
| Sample Disposal <input type="checkbox"/> Return to Client <input type="checkbox"/> Dispose by Lab | | OC Requirements (Specify) Date 2/28/18 Time 12:45 Date 2/28/18 Time 15:40 Date 2/28/18 Time 17:00 Date 2/28/18 Time 17:00 | |
| Note: All samples are retained for four weeks from receipt unless other arrangements are made. | | LAB USE ONLY Received on ice (Circle) <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Ice Pack <input type="checkbox"/> Receipt Temp. 3.1 °C | |

SHEALY ENVIRONMENTAL SERVICES, INC.

Shealy Environmental Services, Inc.
Document Number: ME9018C-11

Page 1 of 1
Effective Date: 01/19/2018

Sample Receipt Checklist (SRC)

Client: SCS Cooler Inspected by/date: CBW / 2-8-18 Lot #: T308087

| | | |
|---|---|--|
| Means of receipt: <input checked="" type="checkbox"/> SESI <input type="checkbox"/> Client <input type="checkbox"/> UPS <input type="checkbox"/> FedEx <input type="checkbox"/> Other: | | |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 1. Were custody seals present on the cooler? | |
| <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> NA | 2. If custody seals were present, were they intact and unbroken? | |
| pH Strip ID: _____ Chlorine Strip ID: _____ | | |
| Cooler ID / Original temperature upon receipt / Derived (Corrected) temperature upon receipt: ____ / ____ / ____ °C ____ / ____ / ____ °C <u>3.1 / 3.1 /</u> ____ °C ____ / ____ / ____ °C | | |
| Method: <input checked="" type="checkbox"/> Temperature Blank <input type="checkbox"/> Against Bottles IR Gun ID: <u>6</u> IR Gun Correction Factor: <u>0</u> °C | | |
| Method of coolant: <input checked="" type="checkbox"/> Wet Ice <input type="checkbox"/> Ice Packs <input type="checkbox"/> Dry Ice <input type="checkbox"/> None | | |
| <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> NA | 3. If temperature of any cooler exceeded 6.0°C, was Project Manager Notified? PM was Notified by: phone / email / face-to-face (circle one). | |
| <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> NA | 4. Is the commercial courier's packing slip attached to this form? | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 5. Were proper custody procedures (relinquished/received) followed? | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 6. Were sample IDs listed on the COC? | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 7. Were sample IDs listed on all sample containers? | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 8. Was collection date & time listed on the COC? | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 9. Was collection date & time listed on all sample containers? | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 10. Did all container label information (ID, date, time) agree with the COC? | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 11. Were tests to be performed listed on the COC? | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 12. Did all samples arrive in the proper containers for each test and/or in good condition (unbroken, lids on, etc.)? | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 13. Was adequate sample volume available? | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 14. Were all samples received within 1/2 the holding time or 48 hours, whichever comes first? | |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 15. Were any samples containers missing/excess (circle one) samples Not listed on COC? | |
| <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> NA | 16. For VOA and RSK-175 samples, were bubbles present >"pea-size" (1/4" or 6mm in diameter) in any of the VOA vials? | |
| <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> NA | 17. Were all DRG/metals/nutrient samples received at a pH of < 2? | |
| <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> NA | 18. Were all cyanide samples received at a pH > 12 and sulfide samples received at a pH > 9? | |
| <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> NA | 19. Were all applicable NH ₃ /TKN/cyanide/phenol/625 (< 0.5mg/L) samples free of residual chlorine? | |
| <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> NA | 20. Were client remarks/requests (i.e. requested dilutions, MS/MSD designations, etc...) correctly transcribed from the COC into the comment section in LIMS? | |
| <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | 21. Was the quote number used taken from the container label? | |
| Sample Preservation (Must be completed for any sample(s) incorrectly preserved or with headspace.) | | |
| Sample(s) _____ were received incorrectly preserved and were adjusted accordingly in sample receiving with _____ (H ₂ SO ₄ , HNO ₃ , HCl, NaOH) using SR # _____. | | |
| Sample(s) _____ were received with bubbles >6 mm in diameter. | | |
| Samples(s) _____ were received with TRC > 0.5 mg/L (if #19 is <i>no</i>) and were adjusted accordingly in sample receiving with sodium thiosulfate (Na ₂ S ₂ O ₃) with Shealy ID: _____. | | |
| SR barcode labels applied by: <u>CBW</u> Date: <u>2-8-18</u> | | |

Comments:



Requested Disposal Facility: 5010 Charlotte Motor Speedway LF NC

| |
|-----------------|
| Waste Profile # |
|-----------------|

Saveable fill-in form. Restricted printing until all required (yellow) fields are completed.

I. Generator Information

| |
|--------------|
| Sales Rep #: |
|--------------|

| | | | |
|--|--|----------------------------------|------------|
| Generator Name: City of Charlotte | | | |
| Generator Site Address: 1536 Tyvola Road | | | |
| City: Charlotte | County: Mecklenburg | State: North Carolina | Zip: 28217 |
| State ID/Reg No: | State Approval/Waste Code: (if applicable) | | NAICS # : |
| Generator Mailing Address (if different): <input checked="" type="checkbox"/> 600 East Fourth Street | | | |
| City: Charlotte | County: Mecklenburg | State: North Carolina | Zip: 28202 |
| Generator Contact Name: Doug Pierotti | | Email: dpierotti@charlottenc.gov | |
| Phone Number: (704) 432-5212 | Ext: | Fax Number: (704) 336-4554 | |

II. Billing Information

| | | | |
|--|--------------------------|-------------------------------|-----------------------|
| Bill To: SCS Engineers | Contact Name: Steve Lamb | | |
| Billing Address: 2520 Whitehall Park Drive | | Email: slamb@scsengineers.com | |
| City: Charlotte | State: NC | Zip: 28273 | Phone: (704) 504-3170 |

III. Waste Stream Information

| | |
|--|---|
| Name of Waste: Former York Rd (Renaissance) Landfill Municipal Solid Waste (MSW) drilling waste | |
| Process Generating Waste: Waste generated from former MSW from closed York Road landfill exploratory drilling | |
| Type of Waste: | <input checked="" type="checkbox"/> INDUSTRIAL PROCESS WASTE <input type="checkbox"/> POLLUTION CONTROL WASTE |
| Physical State: | <input checked="" type="checkbox"/> SOLID <input type="checkbox"/> SEMI-SOLID <input type="checkbox"/> POWDER <input type="checkbox"/> LIQUID |
| Method of Shipment: | <input type="checkbox"/> BULK <input checked="" type="checkbox"/> DRUM <input type="checkbox"/> BAGGED <input type="checkbox"/> OTHER: |
| Estimated Annual Volume: | 5 Drums |
| Frequency: | <input checked="" type="checkbox"/> ONE TIME <input type="checkbox"/> ONGOING |
| Disposal Consideration: | <input checked="" type="checkbox"/> LANDFILL <input type="checkbox"/> SOLIDIFICATION <input type="checkbox"/> BIOREMEDIATION |

IV. Representative Sample Certification

NO SAMPLE TAKEN

| | |
|--|---|
| Is the representative sample collected to prepare this profile and laboratory analysis, collected in accordance with U.S. EPA 40 CFR 261.20(c) guidelines or equivalent rules? | <input checked="" type="checkbox"/> YES or <input type="checkbox"/> NO |
| Type of Sample: | <input checked="" type="checkbox"/> COMPOSITE SAMPLE <input type="checkbox"/> GRAB SAMPLE |
| Sample Date: 02/08/2018 | |
| Sample ID Numbers: 001 - HJGC | |



| |
|-----------------|
| Waste Profile # |
| |

V. Physical Characteristics of Waste

| Characteristic Components | % by Weight (range) |
|---------------------------|---------------------|
| 1. MSW | 50 |
| 2. Soil | 50 |
| 3. | |
| 4. | |
| 5. | |

| | | | | | |
|---------------|-----------------|--|----------|-----|-------------|
| Color | Odor (describe) | Does Waste Contain Free Liquids? | % Solids | pH: | Flash Point |
| Various-black | MSW | <input type="checkbox"/> YES or <input checked="" type="checkbox"/> NO | 100 | NA | NA °F |

Attach Laboratory Analytical Report (and/or Material Safety Data Sheet) Including Chain of Custody and Required Parameters Provided for this Profile

| | |
|--|--|
| Does this waste or generating process contain regulated concentrations of the following Pesticides and/or Herbicides: Chlordane, Endrin, Heptachlor (and its epoxides), Lindane, Methoxychlor, Toxaphene, 2,4-D, or 2,4,5-TP Silvex as defined in 40 CFR 261.33? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Does this waste contain reactive sulfides (greater than 500 ppm) or reactive cyanide (greater than 250 ppm)[reference 40 CFR 261.23(a)(5)]? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Does this waste contain regulated concentrations of Polychlorinated Biphenyls (PCBs) as defined in 40 CFR Part 761? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Does this waste contain concentrations of listed hazardous wastes defined in 40 CFR 261.31, 261.32, 261.33, including RCRA F-Listed Solvents? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Does this waste exhibit a Hazardous Characteristic as defined by Federal and/or State regulations? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Does this waste contain regulated concentrations of 2,3,7,8-Tetrachlorodibenzodioxin (2,3,7,8-TCDD), or any other dioxin as defined in 40 CFR 261.31? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Is this a regulated Radioactive Waste as defined by Federal and/or State regulations? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Is this a regulated Medical or Infectious Waste as defined by Federal and/or State regulations? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Is this waste a reactive or heat generating waste? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Does the waste contain sulfur or sulfur by-products? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Is this waste generated at a Federal Superfund Clean Up Site? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |
| Is this waste from a TSD facility, TSD like facility or consolidator? | <input type="checkbox"/> Yes or <input checked="" type="checkbox"/> No |

VI. Certification

I hereby certify that to the best of my knowledge and belief, the information contained herein is a true, complete and accurate description of the waste material being offered for disposal and all known or suspected hazards have been disclosed. All Analytical Results/Material Safety Data Sheets submitted are truthful and complete and are representative of the waste.

I further certify that by utilizing this profile, neither myself nor any other employee of the company will deliver for disposal or attempt to deliver for disposal any waste which is classified as toxic waste, hazardous waste or infectious waste, or any other waste material this facility is prohibited from accepting by law. I shall immediately give written notice of any change or condition pertaining to the waste not provided herein. Our company hereby agrees to fully indemnify this disposal facility against any damages resulting from this certification being inaccurate or untrue.

I further certify that the company has not altered the form or content of this profile sheet as provided by Republic Services Inc.

Doug Pierotti, Senior Project Manager

City of Charlotte

Authorized Representative Name And Title (Type or Print)

Company Name

Doug Pierotti for City of Charlotte
 Authorized Representative Signature

3-1-2018
 Date

Appendix B

HARRY L. JONES
GOLF COURSE
CHARLOTTE, NORTH CAROLINA

MASTER PLAN

SHEET 1

RON GARL GOLF COURSE DESIGN
704 S. MISSOURI AVENUE
LAKELAND, FLORIDA, 33815
PHONE: 863-688-8383
WEB SITE: www.rongarl.com












DRAWN: R. NIX CHECKED: Ron Garl
DATE: November 14, 2017 SCALE: N.T.S.
Revised - July 6, 2018

| HOLE | YARDS | PAR | HOLE | YARDS | PAR |
|------|-------|-----|-------|-------|-----|
| 1 | 389 | 4 | 10 | 420 | 4 |
| 2 | 123 | 3 | 11 | 155 | 3 |
| 3 | 538 | 5 | 12 | 369 | 4 |
| 4 | 153 | 3 | 13 | 106 | 2 |
| 5 | 517 | 5 | 14 | 545 | 5 |
| 6 | 321 | 4 | 15 | 422 | 4 |
| 7 | 395 | 4 | 16 | 505 | 5 |
| 8 | 319 | 4 | 17 | 400 | 4 |
| 9 | 405 | 4 | 18 | 393 | 4 |
| OUT | 3170 | 36 | IN | 3315 | 36 |
| | | | TOTAL | 6485 | 72 |

PAR 3 COURSE

| HOLE | YARDS | PAR |
|------|-------|-----|
| 1 | 60 | 3 |
| 2 | 100 | 3 |
| 3 | 70 | 3 |
| 4 | 80 | 3 |
| 5 | 90 | 3 |
| 6 | 110 | 3 |
| IN | 510 | 18 |

LEGEND

- Existing Green 
- Existing Centerline 
- Existing Waste Bunker 
- Existing Bunker 
- Existing Tee 
- Proposed Centerline 
- Proposed Chipping Area 
- Proposed Bunker 
- Proposed Mounds 
- Proposed Tee 
- Proposed Green 



HARRY L. JONES
GOLF COURSE
CHARLOTTE, NORTH CAROLINA

MASTER PLAN

SHEET 1

RON GARL GOLF COURSE DESIGN
704 S MISSOURI AVENUE
LAKELAND, FLORIDA, 33815
PHONE: 863-688-8383
WEB SITE: www.rongarl.com












DRAWN: R. NIX CHECKED: Ron Garl
DATE: November 14, 2017 SCALE: N.T.S.
Revised - July 6, 2018


| HOLE | YARDS | PAR | HOLE | YARDS | PAR |
|-------|-------|-----|-------|-------|-----|
| 1 | 389 | 4 | 10 | 420 | 4 |
| 2 | 123 | 3 | 11 | 155 | 3 |
| 3 | 538 | 5 | 12 | 369 | 4 |
| 4 | 163 | 3 | 13 | 106 | 3 |
| 5 | 517 | 5 | 14 | 545 | 5 |
| 6 | 321 | 4 | 15 | 422 | 4 |
| 7 | 395 | 4 | 16 | 505 | 5 |
| 8 | 319 | 4 | 17 | 400 | 4 |
| 9 | 406 | 4 | 18 | 393 | 4 |
| TOTAL | 3170 | 36 | IN | 3315 | 36 |
| | | | OUT | 3170 | 36 |
| | | | TOTAL | 6485 | 72 |

PAR 3 COURSE

| HOLE | YARDS | PAR |
|------|-------|-----|
| 1 | 60 | 3 |
| 2 | 100 | 3 |
| 3 | 70 | 3 |
| 4 | 80 | 3 |
| 5 | 90 | 3 |
| 6 | 110 | 3 |
| IN | 510 | 18 |

LEGEND

- Existing Green 
- Existing Centerline 
- Existing Waste Bunker 
- Existing Bunker 
- Existing Tee 
- Proposed Centerline 
- Proposed Chipping Area 
- Proposed Bunker 
- Proposed Mounds 
- Proposed Tee 
- Proposed Green 



Appendix C

**HARRY L. JONES GOLF COURSE
18 HOLE GOLF COURSE RENOVATION
PRELIMINARY COST ESTIMATE**

Prepared by
RONALD M. GARL GOLF COURSE DESIGN, INC.
704 SOUTH MISSOURI AVENUE
LAKELAND, FLORIDA
PHONE: (863) 688-8383
July 6, 2018

| <u>CONSTRUCTION ITEM</u> | <u>COST</u> |
|---|-------------|
| 1. Selective Clearing (Allowance) | 100,000 |
| 2. Strip Existing Turf from Tees, including Driving Range Tee Haul & Dispose of (160,000 sq.ft. x \$.20 sq.ft.) Sod removed - Hauled and disposed of In House | -0- |
| 3. Strip Existing Turf from Greens Surfaces, Haul & Dispose of (130,000 sq.ft. x \$.20 sq.ft.) Sod removed - Hauled and disposed of In House | -0- |
| 4. Remove Old Greens Mix to a depth of 12 inches & Haul to Tees – In House | -0- |
| 4a. Spread old greens mix & float (4,775 c.y. x \$5 c.y.) | 23,875 |
| 5. Strip Top Soil and stockpile – Holes #10 & #14 - 1 ft. deep = 1,600 c.y. x 4/ac x \$2 | 12,800 |
| 6. Hole #10 & #14 – cut 2/ac on each hole 2.5' deep = 16,000 c.y. x \$3 c.y. | 48,000 |
| 7. Move existing fill from greens and features on the golf course Holes #1, 2, 3, 4, 5, 6, 7, 8, 10, 11, 12, 13 & 17 2,000 c.y. per hole x 13 holes = 26,000 c.y. x \$3 c.y.) | 78,000 |
| 8. Reshape and deepen lake at Green #12 (28,000 s.f. = 6,216 c.y. x \$5.00 c.y.) | 31,080 |
| 9. **Rock Excavation – to be determined by Owners' Rep – Del Ratcliffe | -0- |
| 10. Earthwork – Move Soil from Stockpile to the Golf Course – 72,000 c.y. @ \$3 | 216,000 |
| 11. Rotadation Existing Tees, Fairways and Rough – (94/ac x \$1,100/ac) | 103,400 |
| 12. Rough Shaping – 18 holes, Short Game Area & Driving Range | 200,000 |
| 13. New Automatic Irrigation System – (1,000 heads x \$1,100 per head) | 1,100,000 |
| 14. Pump Station for Irrigation Distribution (Recently Upgraded) | -0- |

| | |
|---|----------------------------------|
| 15. Remove & Dispose of existing greens drainage pipe and gravel – (18 x \$1,000/hole) | 18,000 |
| 16. Rototill Green Sub-Grade - 18 holes, Putting Green & Short Game x \$200/hole | 4,000 |
| 17. New USGA Greens Construction with Granite – 150,000 sq.ft. x \$6 sq.ft. | 900,000 |
| 18. Four-inch Green Outfall Pipe – 150 l.ft. x 25 greens = 3,750 l.ft. @ \$6/l.ft. | 22,500 |
| 19. Four-inch Fairway Perforated Pipe with Granite Rock – 4,500 l.ft. x \$7.50 l.f. | 33,750 |
| 20. Catch Basin – 50 units x \$300 ea. | 15,000 |
| 21. Outfall Pipe – 50 units x 100 ft. x \$8 ft./av. | 40,000 |
| 22. Fine Shaping | 360,000 |
| 23. Plating Topsoil – Holes #10 & #14 - 1 ft. deep = 1,600 c.y. x 4.0 acres x \$2 | 12,800 |
| 24. Laser Level Tee Tops including Range Tee – (176,000 sq.ft. @ \$.15 sq.ft.) | 26,400 |
| 25. New Bunker Construction (includes sand & drainage – 200,000 sq.ft. x \$2 sq.ft.) | 400,000 |
| 26. Installation of new outfall pipe – 81 bunkers x 150 l. ft. = 12,150 x \$6 | 72,900 |
| 27. Dispose of rock and pipe from existing bunkers - - 18 holes x \$500 ea. | 9,000 |
| 28. Cart Paths – Allowance – Owner’s and Engineer’s Responsibility | 475,000 |
| 29. Grassing - Sprig Tees (Celebration - 176,000 sq.ft. @ \$.16 sq.ft. - Hand Plant | 28,160 |
| 30. Grassing - Sprig Fairways including Range (Celebration – 54/ac @ 600 bushels/ac x \$1,500/ ac) | 81,000 |
| 31. Grassing - Sprig Roughs (Celebration – 40/ac @ 600 bushels/ ac x \$1,500/ac) | 60,000 |
| 32. Grassing - Sod (Celebration – 750,000 sq.ft. x \$.55 sq.ft.) | 412,500 |
| 33. Grassing - Sprig Putting Surfaces & Collars (Mini-Verde – 180,000 sq.ft. x \$.52 sq.ft.) | 93,600 |
| 34. As-builts | 7,500 |
| 35. Mobilization, Site prep, Housing, Overhead and Management | <u>155,000</u> |
| SUB-TOTAL | 5,140,265 |
| | Contingency – 15% <u>771,039</u> |
| | TOTAL 5,911,304 |

* Cubic yards, sq.ft. & acreage are an estimate only and shall be revised upon a completed Golf Course Grading Plan.

** Rock Excavation not included.

NOTES:

- a) This estimate does not charge any environmental work to the golf course.
- b) This preliminary estimate will vary for each site depending on specific site conditions.
- c) This estimate represents the golf course designer's best judgement as a design professional familiar with the golf course construction industry. It is recognized, however, that the golf course designer has no control over the contractor's method of determining bid prices or over competitive bidding or negotiating conditions. While the golf course designer cannot and does not warrant or represent that bids or negotiated prices will not vary from the Preliminary Cost Estimate, the Preliminary Cost Estimate represents the golf course designer's best, good faith estimate of construction costs based upon his knowledge of current market conditions and construction techniques.
- d) The owner shall include a contingency amount (as a percentage of the total) which would be applicable to the project, the projects' location, its features and difficulty of the site.
- e) SCS Engineers to determine Best Methods and Means to correct as best as possible the settling on the golf course. This includes any and all drainage, cart paths, Geo Technical fabric to be used on the golf course and etc., etc., etc. and cost for these items. (We have put in an estimate only to move the project along.)

OWNER'S RESPONSIBILITIES

OWNER'S RESPONSIBILITIES:

1. New 6" Topography Map
2. Survey for Centerlines & to Establish Benchmarks
(to be done prior to start of construction)
3. Survey to Verify Fill on the Golf Course
4. Survey to Verify Cut on the Back 9 Holes
5. Maintenance Equipment - additional
6. Landscaping
7. Golf Course Construction Contingency
8. Golf Course Architect fee
9. Professional Fees:
 - Civil Engineer
 - Environmental Engineer
 - Geotechnical Engineer
 - Landscape Architect
 - and Others
10. Project Manager- Owner's Representative
11. Fees – Permits and Recording
12. Easement Locations
13. Signage, Markers, Trash Containers, Benches, Etc.
14. Advertising & Promotional Expenses
15. Grow-In
16. Grand Opening
17. Etc.

**Harry L. Jones, Jr. Golf
Preliminary Construction Cost Estimate
Landfill Related Items**

| | Description | Quantity | Unit | Unit Cost | Extended Cost | Comments |
|----------|--|----------|------|----------------------|--------------------|---|
| 1 | Tees and Greens | | | | | |
| 1.1 | Synthetic Liner for Tee and Greens | 60,000 | SF | \$1.50 | \$90,000 | assumes 8 greens at 7,500 sf each |
| 1.2 | Perforated Pipe for Tee and Greens | 2,000 | LF | \$8 | \$16,000 | |
| 1.3 | Extra Sand Layer Under Liners | 500 | CY | \$30 | \$15,000 | assume 6" layer underneath all liners |
| | | | | Subtotal | \$121,000 | |
| 2 | Soil Surcharging for Fairways, Tees and Greens. | | | | | |
| 2.1 | Move and Place Soil | 129,000 | CY | \$3.50 | \$451,500 | |
| 2.2 | Compact Soil | 129,000 | CY | \$0.50 | \$64,500 | |
| 2.3 | Survey and Monitoring | 1 | LS | \$40,000 | \$40,000 | |
| 2.4 | Remove Soil | 64,500 | CY | \$1.50 | \$96,750 | assumes 1/2 of surcharge soil remains in place. |
| | | | | Subtotal | \$637,750 | |
| 3 | Rapid Impact Compaction for Cart Paths | | | | | |
| 3.1 | Mobilization | 1 | ls | \$50,000 | \$50,000 | |
| 3.2 | Compaction | 90,000 | sf | \$3 | \$270,000 | assumes 3,000 yds of new cart paths. |
| 3.3 | Compacted fill, 3 ft x 8 ft | 8,000 | cy | \$4 | \$32,000 | assume 3 ft of settlement |
| | | | | Subtotal | \$352,000 | |
| 4 | Geogrid Reinforcement | 100,000 | sf | 1.25 | \$125,000 | For select cart paths, tees, and fairways. |
| | | | | Subtotal | \$125,000 | |
| | | | | Subtotal | \$1,235,750 | |
| | | | | Miscellaneous at 10% | \$123,575 | |
| | | | | Contingency at 10% | \$123,575 | |
| | | | | Total | \$1,483,000 | |